

APR 01 1996

COMMISSION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

KALAMAZOO

(County)

Located In:

Corner Code #

TEXAS TWP.

1. Public Land Survey

T 3S R 12W

H9

T R

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Section

S T R

4. Lot No. , Recorded Plat

5. Private Claims

STATE OF MICHIGAN  
COUNTY OF KALAMAZOO  
RECEIVED FOR RECORD

'95 DEC 8 AM 10 55

*James D. Hahn*  
CLERK-REGISTER

LIBER 1 1404

Register of Deeds Stamp & File Number

I, Gary D. Hahn, in a field survey on May 2, 19 95,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found  
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1829 Quarter section corner established by U.S. Deputy Surveyor E.H. Lytle  
Accessories: Bl. Oak 10in S14½W 211. Bl. Oak 14in N12E 181.

1870 F. Hodgman Co. Sur. "1/4 sec. cor. lost - bisected SW. & SE. and found  
the old stake. Planted marked stone over it from which Y. Oak 6 S64E  
62 W. Oak 6 S39W 71."

1981 David Peabody RLS-25866 LCRC Liber 1, Page 822 "Found 1/4" iron"  
Accessories: Centerline rd. 3' North 4" pipe North 33'  
R.R. tie South 22.3'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories not recovered.

Marked stone not recovered.

Found ½" dia. iron rod 3' south of centerline of road. Dug 6' X 8' X 4.5'  
deep hole and probed 2' further. Found nothing. Extended hole 3' north to  
include area under centerline of road. Found nothing.

Section A above continued: 1968 Wilkins & Wheaton Eng. Co. notes: Found  
iron. Distance from found iron to NW. cor Sec. 22 = 2648.20'  
Wightman Ward, Inc. measured 2648.43' between found 1/4" iron  
and NW. cor. sec. 22 on September 20, 1995.

RATIFIED  
BY KALAMAZOO COUNTY  
REMONUMENTATION  
PEER GROUP

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
H9, South Quarter corner Section 22, T3S, R12W, Ratified by Kalamazoo County  
Remonumentation Peer Group on September 21, 1995. Location of iron is accepted  
as the best available evidence of the position of the original corner.  
Removed ½" iron and replaced with a 20" Harrison monument in a monument box.

Set P.K. nail in 50" B. Walnut S70°W 57.06'  
Set P.K. nail in 18" B. Walnut S10°W 22.19'  
Set P.K. nail in R.R. tie fence post South 22.49'  
Set P.K. nail in R.R. tie fence post N5°E 27.54'  
Set P.K. nail in 25" B. Walnut N20°W 39.99'  
Center 4" dia. metal fence post North 33.01'

Signed by

*Gary D. Hahn*

Date December 1, 1995

Surveyor's Michigan License No. 38116

