OUTIVEY G MEMONUMENTATIO

OCT 0 6 1997

J'COMMISSIO"

4. Lot No.

Private Claims

LAND CORNER RECORDATION CERTIFICATE

STATE OF	MICHIGAN
COUNTY OF	KALAMAZO(
RECEIVED !	FOR RECOR!

' 97	Alig	21	PΜ	3	4
01	1100	C 1	1 11	U	

For corners in	Texas Tow	_{mship} Filing Requirem	ent of Act 74, Mich. P.A.	1970	TIT 3 T9
	Kalamazoo County)	Located In:	Corner Code #	Amid	Show
Public Lan	d Survey	T <u>3S.</u> R <u>12W.</u> T R T R T R	J-8	CLERK - RE	EGISTER
Property Control in Section	ontrolling	ST R ST R		LIBER	2PAGE 186
3 . Miscellaned Property in	-	S T R S T R		Register of Deeds Stamp &	File Number

6. IWM JOB NO. 28120	2 6	-5	1	—ģ—	t
	4 7	-8		_10	İ
Allen H. McMachen in a field survey on <u>June 17</u> , 19 <u>97</u> ,	5	1		<u> </u>	ļ
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land	6 18	-17	16-	 15 	-
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a	8 19	20	21		Γ
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	10 30	-29	28	-27-	-

Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

_ , Recorded Plat_

Corner not set by government surveyors. No historic information was found.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Established corner position by intersecting quarter lines. All four quarter corners having been previously ratified.

During excavation for placement of Harrison Monument an iron rod was found 6" below grade (12" long) at exact position of computed location.

> BY KALAMAZOO COUN **REMONUMENTATIOI** PEER GROUP 7-16-1997

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

This position not established by original government surveyors. Point of intersection of quarter lines is accepted as the best available evidence of the position of the corner. Placed Harrison monument at point of intersection of quarter lines, Accessories:

Nail & Tab in West side 10' Oak N. 04° E. 45.30'

Nail & Tab in Northwest side 6" Oak N. 40° E. 9.98'

Nail & Tab in North side 10" Elm S. 86° E. 7.43'

Nail & Tab in West side 8" Oak South 10.51"

Signed by Surveyor's Michigan License No.

ALLEN H. McMACHEN **PROFESSIONAL** SURVEYOR No. PROFESSIONAL