SUEVEY & REMONUMENTATION

FEB 0 8 2000

, Recorded Plat

Sequence #/

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

4. Lot No. 5. Private Claims

2

SECTION

Kalamazoo		Located In:	Corner Code#
(County)		,	
Wakeshma Twp.			
1. Public Land Survey		T <u>4S</u> R <u>9W</u>	D-7
•	-	T R	
		T R	
		Ť R	
2. Property Controlling	S	R	
in Section	s	TR	
3. Miscellaneous	s	_ TR	
Property in Sec.	S	T R	

2PAGE 452 LIBER RECEIVED FOR RECORD SESE

Register of Deeds Stamp & File Number

·			
I, Gary D. Hahn	, in a field survey on	October 29	, 19 <u>98</u>
do hereby state that under re	equirements of P.A. 74, Mich	igan P.A. of 1	970, the corner
points mentioned in lines 1 a	nd 2 above were in conforma	ance with regul	ations and rules
therefore as required in the	current manual of survey ins	tructions of th	e United States
Department of the Interior, Bu	reau of Land Management or	by a decree of	a Court of Law
and /or that the corner points	s mentioned in lines 3, 4 and	5 above were	in conformance
with the rules of the Michigan	Board of Land Surveyors or I	by a Decree of	a Court of Law:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

established, re-established, monumented, recovered, found as expressed below:

- 3 4 5 6 7 8 q 11
- A. Description of original monument and accessories and/or subsequent restoration:
- 1826 Quarter post established by U.S. Deputy Surveyor Robert Clark, Jr. Beech 7" N 4 E 26 lks. Beech 10" S 84°W 21/2 lks.

1866 - F. Stimson "Gov. comer lost. Established midway between A & C. Set long pointed flatish stone, top 2 or 3 inches out of ground. Charcoal near top of stone". Gives distance of 40.215 CH. - 2654.19' to SE. & SW. corners.

KCRC Witness Ties:

12" - 14" Twn. Maples S 79.40 Iron S 45°W 91.05'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories not recovered.

1998; No surface marker found. Excavated 6' (N & S) x 12' (E & W) x 7' deep hole centered on bisection. Found a 1" x 2" wood stake standing erect at a depth of 4.5' just below old road bed. Found no evidence of stone. Stake in line with tree line & fence line to south. Stake was 4.3 + N 45°E of bisection. Reestablished corner at the bisection of the previously ratified southwest and southeast corners of section 17.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-7, South Quarter Post, Section 17, Town 4 South, Range 9 West. Ratified by the Kalamazoo County Remonumentation Peer Group on December 17, 1998. Set a 30" Harrison Monument in a monument box at the above described bisection. This position is accepted as a careful and faithful reestablishment of the position of the original corner.

Set Mag. Nail in 12" Maple S 5°E 41.71'

Set Mag. Nail in R.R. tie fence post South 29.55'

Set ½" rebar @ edge of asphalt N 20°W 19.96'

Set ½" rebar @ edge of asphalt N 47°E 22.91'

RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP 12-17-1998



Surveyor's Michigan License No

Date 02/09/99 FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS,

JAN.28,1971