



LC-000028
Page: 1 of 1
09/17/1999 03:11P
Bk-2 Pg-481

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Schoolcraft Twp.

Kalamazoo (County)	Located in:	Corner Code #
1. Public Land Survey	T 4 S R 11 W	K-13
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

SURVEY &
REMONUMENTATION

FEB 08 2000

SECTION

Register of Deeds Stamp & File Number

I, Robert E. Snell, in a field survey on June 25, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1825: United States Government Surveyors, J. Mullett; set post, corner to Section 34 and 35.

Tamarack 4" N. 88° E. 245 lks. Wh. Oak 16" N. 89° W. 891 lks.

1889: F. Hodgman, County Surveyor; (for) "Southeast corner ran East, true line 40.32 chains from S. 1/4 post and set post 18 lks. West of corner of Sections 1 & 2 Park (Twp.) stone.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1916: G. Eagleton, County Surveyor (St. Joe); corner to Section 1 & 2 Park - corner under culvert in swamp.

1999: Found 1/2" iron for Park Twp. corner and PK Nail 10.90' West for Schoolcraft corner. Found stone for Park Twp. and measured 11.88' to find Schoolcraft tile. One foot of tile was laying on its side with a 2 ft. section in proper position. PK Nail was 4.05' South and 2.2' West of the position of the tile. Placed 1/2" iron in monument box over top of stone for Sections 1 & 2, Park Twp., 11.84' East of tile.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-13: Southeast corner, Section 35, T. 4 S., R. 11 W., ratified by the Kalamazoo County Remonumentation Program Peer Group on August 19, 1999 and is accepted as a careful and faithful perpetuation of the position of the original corner. Found a 2 foot section of 3" round tile with a 1 foot section laying on its side over. Both tiles had "x" on top and were 1.75' below surface of the road. Tile was set by F. Hodgman in a 1889 Remonumentation survey. Placed remonumentation tile sleeve over 2' section of tile and a 20" Harrison monument in a monument box over it.

PK Nail in South Side	Group of 5" Maples	N. 68° E.	57.85'
PK Nail in North Side	Group of 5 Willows (13")	S. 60° W.	35.47'
Center line of 15" Culvert	North End	N. 48° W.	42.60'
PK Nail in East Side	Wood Fence Corner	North	36.00'

Signed by Robert E. Snell
Surveyor's Michigan License No. 9734

Date 9-16-99

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
8-19-1999