

MAY 16 1957

COMMISSIONER

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER003 PAGE0351

For corners in

Lake (County)	Located In:	Corner Code #
1. Public Land Survey	17N 11W T R T R T R T R	E-5
2. Property Controlling in Section	S T R S T R	
3. Miscellaneous Property in Sec.	S T R S T R	

RECORDED  
LAKE COUNTY, MI.  
SEP 12 3 07 PM '96  
REGISTER OF DEEDS  
*James H. Davis*

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Robert L. Wetherell, in a field survey on August 6, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-5 - Section corner common to Sections 8, 9, 16 & 17, T17N, R11W, Chase Twp., Lake Co., Mi.

1838 - John Hodgson, G.L.O.

#1 - 8" Beech S45°E 32 Links

#2 - 9" Hemlock N34°E 11 Links

Undated - George Johnson, Co. Sur. (1920's)

Drag Tooth for corner

#3 - 7" W. Pine N37°W 130'

1980 - Lakestate Surveyor's,

Clint Cole, LS 17615

Set 1/2" Iron over Drag Tooth

#4 - Pine N36°E 84.14'

#5 - 6" Locust S45°W 99.87'

#6 - 8" Maple N52°W 84.88'

1993 - Jerry Taylor, LS 32342

L.C.R.C. dated Jan. 21, 1993

1/2" Iron Rod for monument

#7 - Face of Tel. Pedestal

S45°W 51.20'

#8 - Face of Tel. Pedestal

N45°E 67.6'

#9 - Utility Pole S75°E 128.88'

#10 - 9" Aspen N50°W 68.27'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-5 - Section corner common to Sections 8, 9, 16 & 17, T17N, R11W, Chase Twp., Lake Co., Mi.

I found a 1/2" iron rod over old drag tooth in the intersection of roads North, South, East and West.

Condition of accessories are: #1. Gone, #2. Gone, #3. Gone, #4. Found in good condition, #5 Found in good condition, #6. Found in good condition, #7. Found in good condition, #8. Found in good condition, #9. Found in good condition, #10. Found in good condition.

RATIFIED BY THE LAKE CO. PEER REVIEW GROUP

IN ACCORDANCE WITH P.A. 345

CHAIRMAN

DATE - 8-27-96 *R.L.W.*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-5 - Section corner common to Sections 8, 9, 16 & 17, T17N, R11W, Chase Twp., Lake Co., Mi.

I replaced the 1/2" iron rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithful re-establishment of the position of the original corner.

10" S. Pine N35°E 84.22' (60d spike in W. side) #4

11" Locust S47°W 99.82 (60d spike in E. side) #5

12"-5" Twin Maple N54°W 85.02' (60d spike in S. side) #6

8" Tamarack S7°E 91.36' (60d spike in W. side)

Signed by *Robert L. Wetherell*

Date August 28, 1996

Surveyor's Michigan License No. LS-24624

