

JAN 2 5 2001

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

S	F	C	ľ	l)	١

Foi L <u>al</u>	r corners in ke		Loca	ated in:	Corner Co	de#		M			-		121 10	ļ
1. Public Land Survey			٦	T 17 N	R 14 W	C-4		MA	1 3	10	26	Ali (JU	
			•	T	_ <u>R</u>			A	Alex		1772	yea	لن	
			T		<u>R</u>			Aduly Myers REGISTER OF DEEDS						
				<u>T</u>	R									
Property Controllin in Section	s	<u>T</u>		_R										
	in Section	s	<u>T</u>		R	- And Andrews Control of State Control o	Registe	er of l)eeds	Stem	nn & F	ile Ni	ımhe	r
Miscellaneous Property in Sec.	s	T	 	R	<u> </u>	riogiote	51 01 1	, , , , , , , , , , , , , , , , , , ,		·p ·				
	s	Т		_R										
	Lot NoRecor	ded Pla	at				4	а в	CDI	EFC	H 1	JE	LM]
5.	Private Claims						1 2	6	5	4	3	2	1	
i, Robert L. Wetherell, in a field survey on March 10, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner							3 4	7.	8	9	10	11	12	
points mentioned in lines 1 and 2 above were in conformance with regulations and						5		4-7	40	45	44	40		
rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a						6 7	18	17	16	15	14	13		
Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were					8	19	20	21	22	23	24			
In conformance with the rules of the Michigan Board of Land Surveyors or by a Decree						9 10	30	29	28	27	26	25		

A. Description of original monument and accessories and/or subsequent restoration:

1838 - J. Hodgson, G.L.O. #1 - 12" Hemlock S62°E 15 Links #2 - 12" Elm N29°W 27 Links

recovered, found as expressed below:

C-4 - 1/4 Corner common to Sections 7 & 8, T17N, R14W

1908 - J.W. Nichoson, Co. Sur. "Set temporary post" No witnesses taken.

#3 - Measured 2674.98 feet North to Section corner.

1956 - G. Blass, LS 5489

34

32

33

36

35

RECORDED LAKE COUNTY, MI.

Found rotted wood stake and 1/2" x 1' Iron Bar #4 - P. Pole N10°E 140.00' #5 - 8" Square Conc. Mon. Fence Post (W. side) East 30.60'

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

I found a 1/2" bar in line with fences East and West and 3 feet more or less East of the centerline of road North and South.

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Measured 2695.14 feet, #4 Found in good condition, #5 Found in good condition.


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the 1/2" bar with a 3/4" x 24" rebar with Lake County Remon Cap, and is accepted as a careful and faithful reestablishment of the position of the original corner.

MAGGE.

P. Pole N15°E 140.03' (60d spike S.E. side) Top Center of 8" X 8" Square Conc. Post - East 30.86' (#5) 4" Maple (Clump of 5) West 62.66' (60d spike N. side) P. Pole S04°E 241.87' (60d spike E. side)

AGUCA PARP MEVIEW GROUP EATH CHEELPA, 345 CHASTAIN R.R.W. WATE H-11-2000



Kobert J. Wetherell Surveyor's Michigan License No. 24624

Date April 12, 2000

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 ADAPTED FOR WORD PROCESSING JANUARY, 1999