SURVEY & REMONUMENTATION

MAR 1 3 1998

1997 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

RECEIVED TOT TECORD

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970

97 NOV 12 PM 2: 39

For corners in: DEERFIELD TWP.				M. Kasa Do Vaugh						
LAPEER (County)	Located In:	Corner Code #		Makisaa Da Vangh REGISTER OF CEEDS LAPEER CAUTTY FOR SIGAR						
Public Land Survey	T R				LAPEER FLUMS AND HEAR					
Property Controlling S. in Section S. Miscellaneous S. Property in Sec. S.	T R T R		Reg	ister of D	eeds S	Stamp 8	k File N	lumbei	Γ 	
				, A B C	D	E F G	• H I	J K	L	
4. Lot No, Rec 5. Private Claims	orded Plat			2 6	· · · 5	4	ვ	2	j	
				3 - 7	8	9	10	11	12	
I, JONATHAN M. FIELD in a field survey on JUNE 19 97 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5			5 6 18	17	-16	15	14	13		
			7	- 20	21	22	23	- 24		
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:		ound as	9 30	29	28	27	26	-25		
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			11 3:1····	32	33	34	35	36		
1834 GLO; BURNHAM, D 1977 BECK-GRAVLIN; BI S30W 88.18' P-K 1979 BECK-GRAVLIN; BI 1979 GRAVLIN SURVEYI GRAVLIN SURVEY 1979 GRAVLIN SURVEY	ECK, P.S.#21559; SURVE NAIL IN 30" MAPLE, S20 ECK, P.S.#21559; SURVE ING; GRAVLIN, P.S.#235 ⁻ EY CITED ABOVE	PRIGINAL GOVERNMEN EY; L.004,PG.377; FND. ! E 46.75' P-K NAIL IN 38' EY; L.005,PG.571; FND. 10; SURVEY; L.009,PG.	11 SURVEY MON. BOX; " OAK 1/2" ROD; 1 368; FND. 1	N70°E 13 O WITS KOB .NON	GIVEN (; SAM	i E WITS	S AS 19	977 BE	CK-	
A-4 TO A-3 2693.29' GR A-5 TO A-5 2607.27' RE	AVLIN '91, 2693.12' REI ' '97	·97 A	∖-4 TO M-4	234.30' A 196.74' I						
B. Description of corner et 1997 ROWE; FIELD, PS#	vidence found and/or method #37276; FND. 1/2" ROD A	d applied in restoring or rees T C/L GRAVEL ROAD N	stablishing co I-S & ON O	rner: CC, TREE	ELINE	TO E.				
A-4 1/2" ROD W/ STAND S45°W, 47.27' S35°W, 74.14'	ent for corner and accessorie DARD REMON CAP FND. 1/2" ROD W/ CAP # FND. 1/2" ROD W/ CAP #	£23510 £23510	locating the p	oosition of t	the corr	ner:	ICH G			

S70°E, 35.52' P-K NAIL W/ REMON TAG IN S. FACE T.POLE

N85°W, 34.76' 2" ANGLE IRON COR. FENCE POST IN CONC. N70°E, 17.96' P-K NAIL IN S. FACE 14" OAK \$20°E, 47.19' P-K NAZIL IN E. FACE 38" OAK

NORTH, 17.48' FND. 1/2" ROD SOUTH, 196.74' 1/2" ROD W/ REMON CAP AT M-4 T9N-R9E

RAY DAVISHS, UC. SURVEYOR DAVE 9-29-97

Ù

M. FIELD

PROFESSIONAL SURVEYOR