

NOV 07 1994

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 25

For corners in Lenawee (County)	Located In:	Corner Code #	FILED 10:56	¹ €
1. Public Land Survey	T <u>- 5 - S</u> R <u>- 4 - E</u> T R T R T R	<u>H-13</u>	OCT 28 1994 LENAWEE COUNTY JEANETTE D. MOX REGISTER OF DEEDS	
 Property Controlling in Section Miscellaneous Property in Sec. 	STR STR STR STR		Register of Deeds Stamp & File Num	
4. Lot No, F 5. Private Claims	Recorded Plat		1 2 5 5 4 7 8 9 10 11	12
do hereby certify that under in lines 1 and 2 above wer current manual of survey ins Management or by a decree above were in conformance	, in a field s requirements of P.A. 74, Michigan F e in conformance with regulations tructions of the United States Dep of a Court of Law and/or that the co with the rules of the Michigan Boa l, re-established, monumented,	P.A. of 1970, the corner points me and rules therefore as required artment of the Interior, Bureau of orner points mentioned in lines 3, and of Land Surveyors or by a Dec	nentioned 7 ed in the 8 of Land 3, 4 and 5 ecree of a 10 30 29 28 27 26	24 25 36
NOTE: Not more than 4 on this certificate	comers, all in the same town e. e.	and range, may be recorded	13	

Description of original monument and accessories and/or subsequent restoration:

G.L.O. June 1819, Joseph Fletcher set 1/4 Sec post, Dogwood 6 S 15 E 2, W Oak 30 S 62 E 41. Subdivision of the section on survey of around 1840 shows the corner but no description of the monument. 1957-1958, K.L. Suydam re-established the corner (set iron) by retracing a survey from the north and a found iron

pipe on the section line 133.2 to the West. The corner is shown on Assessor's Plat No. 6, City of Tecumseh, recorded in L 14 of Plats, Pages 15, 16 and 17, in

1967, I found an iron pipe 12" deep as per Assessor's Plat No. 6.

April 8, 1976, K.L. Suydam recorded the corner in L 3, P 383.

В. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

September 23, 1994, Found iron pipe 8" deep which checked the remaining witnesses. Replaced the iron pipe with a 30" Harrison monument and marked with a carsonite post.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

30" Harrison monument stamped P.S. 13040 and is accepted as the best available evidence of the position of the original corner.

SE corner of house foundation N 35° W 82.52 Dbl. hd. nail & disc in 36" Oak N 20° E 80.82 Dbl. hd. nail & disc in 24" Elm N 50° E 32.32 Dbl. hd. nail & disc in Elec pole S 60° W 50.50 N 1/4 cornerSection 3, T6S-R4E West 333.67

> // Date <u>9-29-94</u> Date Oct. 10, 1994

MICH GLENN E RICHARD No. 13040

Ratified by Peer Group in accordance with P.A. 345

John & Richard Signed by_

Clenn E. Richard

Surveyor's Michigan License No. 13040