

JAN 22 2001

Filed under Remonumentation Act 345 of 1990

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Lenawee
(County)


Located in:

Corner Code #



LIBER 1

PAGE 425



1. Public Land Survey T - 6 - S R - 2 - E M - 3
 T R
 T R
 T R
2. Property Controlling S T R
 in Section S T R
3. Miscellaneous S T R
 Property in Sec S T R

Register of Deeds Stamp & File Number

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

I, Glenn E. Richard in a field survey on June 2, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1824 Harvey Parke D.S. Set post corner Sec.'s 1 & 12 Maple 16 S 84 E 5 W. Ash 6 N 78 W 40 1/2
 1927 J.L. Richard and Harold Clegg surveyed the road from Adrian to Onsted. The plans call for "Sta. 343+48.8 SE corner Section 1 gas pipe
 1960 I found iron pipe and replaced it with a new galv. pipe
 1964 Kenneth Suydam found iron
 1966 Kenneth Suydam found iron bent, straightened and reset
 1974 Kenneth Suydam used corner. Doesn't show type of monumentation
 1975 I found 1" galv. pipe and recorded it in Liber 3, Page 264
 1977 Werner Sommer found iron
 1978 Kenneth Suydam found iron
 1978 I found 1" iron pipe
 1981 Kenneth Suydam found bolt
 1995 Michael Bartolo found railroad bolt over 1" iron pipe 13" deep & recorded it in Liber 5, Page 266

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

June 2, 2000 Found railroad bolt all bent. The top was 0.08 S & 0.07 E of the 1" X 30" galv. pipe I found 13" deep. I replaced the galv. pipe with a 30" Harrison Monument stamped P.S. 13040 with the top being 6" below the surface.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

30" Harrison Monument stamped P.S. 13040 and is accepted as the best available evidence of the position of the original corner.

Face of gas pipeline marker N 35° E 42.76
 NE corner of garage foundation S 20° W 129.25
 NE corner of brick burner S 80° W 122.53
 Set dbl hd nail & re-mon tag in NE face of 36" Ash N 45° W 100.64
 Fd. nail and disc in 36" Willow stump N 30° W 80.07



Ratified by Peer Group in accordance with P.A. 345 Co. Reg. Glenn E. Richard Date August 8, 2000

Signed by Glenn E. Richard Date Sept. 28, 2000

Glenn E. Richard

Surveyor's Michigan License No. 13040