

DEC 2 2 1998

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

PAGE 305 LENAWEE COUNTY FILED

SECTION

For corners in Lenawee	Located In:	Corner Code #	16 DEC 1998 4:20:17 PM
(County)			VICTORIA J. DANIELS
Public Land Survey	T -6-S R - 3 - E T R T R	1-9	REGISTER OF DEEDS
2. Property Controlling S_ in Section S	TR		
3. Miscellaneous S_ Property in Sec S	T R		Register of Deeds Stamp & File Number
I, Glenn E. Richard do hereby certify that under require lines 1 and 2 above were in current manual of survey instruction. Management or by a decree of a Cabove were in conformance with	, in a field irements of P.A. 74, Michigan conformance with regulations ons of the United States Decourt of Law and/or that the otherules of the Michigan Boo	I survey on <u>November 4</u> 19 P.A. of 1970, the corner points mentice and rules therefore as required in partment of the Interior, Bureau of Eorner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree re-monumented, recovered, found	3 4 7 8 98 98 98 98 98 98 98 98 98 98 98 98 9
NOTE: Not more than 4 co on this certificate.	orners, all in the same to	own and range, may be record	
A. Description of original n	nonument and accessorie	s and/or subsequent restoration	:
			S 75 W 41, B. Oak 6 N 36 E 24

1919 The road was surveyed by J.L. Richard "Sta 106+64.5 center line S 1.4 post Sec. 22 P.I. defl 0°05' L. 1948 Harold Clegg found bolt in pavement. 1935 witnesses 14" Maple SW 41.1, 14" Hickory SE 45.9 August 1971, Kenneth Suydam found 1" solid rod in monument box and recorded it in L. 1, P. 165 and L. 1, P. 261, nail in 24" Maple SW. 40.75

January 1972, Werner Sommer "Found re-rod in monument box" Fd. nail & washer in 24" Maple S 48° W 70.79, Fd. nail & washer in 22" Hickory S 60° E 62.38

January 1975, Kenneth Suydam "Found monument box" nail & washer in 24" Maple SW 40.75, nail & washer in 28" Hickory SE 62.35 and recorded it in L. 3, P. 91

1979-1980, Adrian Township constructed a sewer system and dup up the intersection, a manhole is 3' ± W of the Sec. corner. Monument box was reset by Consulting Engineers after sewer construction.

The Plat of Hunt Valley is tied to this corner & field work was done prior to sewer construction.

1984, There was some confusion as to the location of this corner since the sewer construction due to sewer P.K. nails in the vicinity of the monument box. I did some re-tracing of surveys done before the sewer construction which checked the location of the 3/4" iron pipe in the monument box and recorded it in L. 5, P. 131

May 1, 1997, Fd. 3/4" iron pipe in mon. box which checked the witnesses shown on L.C.R.C. recorded in L. 5,P. 131

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

July 1998 Sewer contractor dug out comer while tapping into Manhole 2.5 SW. November 4, 1998, Set 5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 and monument box using witnesses shown on Lenawee County Remonumentation corner recorded in L. 1, P. 170

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" iron pipe capped G.E.R. in monument box and is accepted as the best available evidence of the position of the original corner.

Fd. dbl. hd. nail & disc in Elec. pole N 60° W 54.91

Fd. dbl. hd. nail & disc in 24" Maple S 45° W 41.85

Fd. dbl. hd. nail & disc in 26" Hickory stump S 60° E 63.65 Fd. dbl. hd. nail & disc in 30" Chinese Elm S 75° E 99.66

Fd. dbl. hd. nail & disc in Tel. pole N 50° E 45.88

NW. corner of west porch of house S 45° E 101.47

No. 13040 BYONAL ST John Richard Date December 1, 1998

Ratified by Peer Group in accordance with P.A. 345

Glenn E. Richard

Date Dec. 11, 1998

Co. Rep

Surveyor's Michigan License No. 13040

MICHIGA

GLENN E

RICHARD