

JAN 22 2001

Filed under Remonumentation Act 345 of 1990

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Lenawee
(County)

Located In:

Corner Code #



LIBER 1

PAGE 407

1. Public Land Survey

T 6-S R 4-E

C-8

T _____ R _____

T _____ R _____

T _____ R _____

2. Property Controlling
in Section


S _____ T _____ R _____

S _____ T _____ R _____

3. Miscellaneous
Property in Sec

S _____ T _____ R _____

S _____ T _____ R _____



Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Glenn E. Richard, in a field survey on August 10, 2000,

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1819 Joseph Fletcher D.S. Set 1/4 Sec. post W. Oak 12 S 64 W 154 W. Oak 16 N 47 W 197

1888 James Blair found stake and stones. 8" B. Walnut S 1° E 39 (25.74')

1926 Walter Frazier found lime & stake. Drove angle iron. 18" Walnut S 1° E 38 1/3 lks (25.30')

1954 P.O.B. Plat of 1st Addition to Suburban Acres

1961 I found angle iron

1965± Jack Gillin (Lenawee County Road Commission Employee) found large angle iron bent and lime. Replaced it with 2" iron pipe. Spike & flasher in W. side 20" Walnut S 2° W 26.31, Spike & flasher in E. side 13" Hickory N 35° E 32.55

Spike & flasher in S. side 18" dbl Oak N 45° W 44.64, P.K. in N. side 18" Walnut S 55 E 47.80

1967 I found iron pipe. Plat monument North 33'

1972 Werner Sommer found iron pipe and recorded it in Liber 2, Page 19 and used same witnesses as Jack Gillin

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

August 10, 2000 Kevin Pickford P.S. 46682 Found 60d spike (bent) in top of 1 1/4" X 27" iron pipe. Replaced the iron pipe with 5/8" x 3' re-rod with Lenawee County Re-mon capped P.S. 13040 and set monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as a careful and faithful perpetuation of the position of the original corner.


Replaced found nail & 3 1/2" Alum. disc with dbl hd nail & re-mon tag in W. face of 24" Walnut South 26.33

Fd. dbl hd nail & 3 1/2" Alum. disc in S. face 23" dbl Oak N 55° W 44.42

Fd. dbl hd nail & 3 1/2" disc in S. face 13" Hickory N 25° E 32.52

Set dbl hd. nail & re-mon tag in N. face of 27" Walnut S 65 E 47.80

Plat monument North 32.93



Ratified by Peer Group in accordance with P.A. 345

Co. Rep. Glenn E. RichardDate August 22, 2000Signed by Glenn E. RichardDate Sept. 15, 2000

Glenn E. Richard

Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

ADAPTED FOR WORD PROCESSING MARCH, 1993