

JAN 22 2001

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Lenawee

(County)

Located in:

Corner Code #



LIBER 2

PAGE 18

1. Public Land Survey

T-7-S R-2-E

A-5

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in S

S T R

S T R

STATE OF MICHIGAN
LENAWEE COUNTY
FILED

5 DEC 2000 9:47:11 AM

VICTORIA J. DANIELS
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No.

Recorded Plat

5. Private Claims

I, Glenn E. Richard, in a field survey on October 4, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1824 John Mullett D.S. Intersect w. bdy. 44L S. of post. Set post at intersection cor. Sec. 7 & 18 B. Ash 6 N 15 E 10 B. Ash 8 S 69 E 22
1887 James Blair found a stone 44 lks south of iron bar and stone @ M-5 T7S R1E
1925 Walter Frazier survey for MSHD "gas pipe @ surface of stone road. NE corner of conc. hdwl. N 69° W 38.95 NW cor. of conc. hdwl. N 71° E 39.5 SE cor. of conc. hdwl. S 62° W 41.24
1953 Harold Clegg P.S. 13578 found iron pipe at surface of black top.
1956 Kenneth Suydam P.S. 17636 found iron
1972 I found iron pipe

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

October 4, 2000 Found 1" galv. pipe 4" below surface of the pavement. The galv. pipe was 1" X 23" and had pieces of brick in the bottom. Probed and hit bricks along the E. side of found galv. pipe. Didn't hit any stone. Set 5/8" X 3' re-rod 0.03 west of found galv. pipe to be on line between A 5 & 6 T7S R1E. Placed Lenawee County Re-mon cap stamped P.S. 13040 and set monument box in base course of new asphalt pavement.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Remon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

NW corner of concrete hdwl N 70° E 39.60
SE corner of concrete hdwl S 61° W 41.42
NE corner of concrete hdwl N 69° W 39.07
Dbl hd nail & re-mon tag in T.P. N 36° W 37.76
fd. nail & disc in E.P. S 15° W 66.27

M-5 T7S R1E North 29.10



Ratified by Peer Group in accordance with P.A. 345 Co. Reg. Glenn E. Richard Date November 28, 2000

Signed by Glenn E. Richard Date Nov. 29, 2000
Glenn E. Richard

Surveyor's Michigan License No. 13040