

OCT 21 1997

COMMISSION

Filed under Remonumentation Act 345 of 1990
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 1 PAGE 200

STATE OF MICHIGAN
LENAWEE COUNTY
FILED

9 OCT 97 3:42 P.M.

VICTORIA J. DANIELS
REGISTER OF DEEDS

For corners in

Lenawee
(County)

Located In:

Corner Code #

- | | | | |
|------------------------------------|----------------|----------------|------------|
| 1. Public Land Survey | T - <u>9-S</u> | R - <u>1-E</u> | <u>G-3</u> |
| | T | R | |
| | T | R | |
| | T | R | |
| 2. Property Controlling in Section | S | T | R |
| | S | T | R |
| 3. Miscellaneous | S | T | R |
| Property in Sec | S | T | R |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Glenn E. Richard, in a field survey on Aug. 6, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. Ziba Swan set post cor Sec 3, 4, 9 & 10 W. Ash 8 S 79 W 7 Beech 5 S 75 E 22
1919 Walter Frazier surveyed Morenci Rd. and referred to the corner by station and being 48.7 South of the centerline.
1969 Kenneth Suydam retraced the road survey and dug but didn't find anything and set a thin wall
1" X 36" iron pipe.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Aug 6, 1997 I found a short iron rod in top of the 1" X 36" iron pipe in a monument box. Replaced the thin wall 1" X 36" iron pipe with a 3/4" X 36" iron pipe capped G.E.R. 13040

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' iron pipe capped G.E.R. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.
Fd dbl hd nail & disc in EP S 20° W 60.71
cut "X" on N. end of CMP S 50° E 26.76
cut "X" on S. end of CMP S 20° E 59.97
Road & Stop sign post N 15° W 92.52
Face of round telephone pedestal N 55° E 54.13

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date September 9, 1997

Signed by Glenn E. Richard Date Sept 19, 1997
Glenn E. Richard

Surveyor's Michigan License No. 13040