

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Luce</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T 45N R 10W	M12
	T R	
2. Property Controlling in Section	S 36 T 45N R 10W	14
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

I, Stephan J. Szyszkoski, in a field survey on 14 04/16/2012 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(14-Sec. 36) South 1/16 corner between Section 36 T45N-R10W and Section 31 T45N-R09W. Not previously
monumented.

(M12) Quarter corner common to Section 36 T45N-R10W and Section 31 T45N-R09W. 2001 - Corner monument
approved by Luce County Peer Review and recorded in Liber 3, Page 1003, Luce Co. land corner records.
1" pipe with MI Dept. of Conservation cap. 11" Beech N31E 32.22', 18" Sugar Maple S62E 24.16', 7"
Ironwood S07E 19.71', 6" Ironwood N65W 5.83'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14-Sec. 36) Established the position for the corner midway and on the Range line between Township
corner 1319.03' south and Quarter corner 1319.03' north. From the position thus established I found
a 1.5" I.pipe projecting 2.2 ft, set by persons unknown for an approximate corner, S89W 64.3'
distant.

(M12) Found the monument of record in good condition and at record bearing and distance from the 2001
witnesses recovered as follows: 11" Beech now a stump, 18" Sugar Maple now dead, 7" Ironwood S07E
fallen down, 6" Ironwood N65W in good condition. Accepted the monument and made new witnesses as
described below. In addition, the OBT Sugar noted in the DeLaMater 1952 record and restated in the
2001 record is now a stump at record bearing and distance.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
12" Sugar N84W 46.95' mrkd "S1/16 BT"
6" Cherry N70E 8.45' do
10" Sugar S20E 16.7' do
8" Hemlock S55E 19.7' do
Set sq'd Hemlock post adjacent.
Bearings are magnetic.

(M12) Fd. 1"ID I.pipe with 4" brass MI Dept.
of Conservation cap.
Set measuring nail with MDNR tag in the side of:
13" Sugar S31W 12.75' mrkd "1/4S NBT"
15" Sugar S35E 14.05' do
10" Sugar N28E 44.05' do
7" Ironwood N56W 5.95' (exist. nail 2001 NBT)
Bearings are magnetic.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/12/2012

For the Michigan Department of Natural Resources, Forest Resources Division

