

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Luce</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T 46N R 10W T 46N R 11W T 47N R 10W T 47N R 11W	A1 Same M1 Corner A13 (Township M13 Corner)
2. Property Controlling In Section	S T R	
3. Miscellaneous Property in Sec.	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3								
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Stephan J. Szyszkoski, in a field survey on 05/17/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A1) Corner common to Townships 46N-47N and Ranges 10W-11W. Corner reviewed and approved by Luce Co.
Remuneration Peer Group Nov. 27, 1996 and recorded in Liber 2 of LCR, Page 703. Keith R. Waters
PS found a Michigan Dept. of Conservation brass capped pipe monument and made the following
witnesses: 12" Red Pine S04W 38.59', 10" Red Pine S49W 64.52', 9" Cherry N30W 29.15', 8" Cherry N02W
27.78'. The distances are to a nail/tag P.S. 33142 in the side of the witness object.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A1) The monument was not recovered, likely having been destroyed by nearby earth-moving activity.
The 1996 witnesses were all recovered in good condition, as described, with all blazes open and
measuring nails present. Reestablished the corner position at record bearing and distance from the
1996 witnesses of record.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A1) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Fd. measuring nail with Tag 33142 in the side of:
14" R.Pine S08W 38.6' with open blazes.
11" R.Pine S53W 64.5' do
9" Cherry N25W 29.15' do
8" Cherry N02E 27.75' do
Bearings are magnetic.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 10/26/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971