

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 27 T 50N R 9W	11
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 05/29/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(11-Sec. 27) Southwest 1/16 corner, Section 27. 1964 - Established and monumented by F.J.Bray RLS:
"This corner was placed on mean bearing between Section line to West and 1/4 line to East and at the
average measurement of lines in vicinity". Set 1" iron pipe with 4" aluminum cap. 15" R.Pine S02W
30.5 links, 10" W.Pine N24E 22 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(11-Sec. 27) The 1964 monument has been removed by earthwork. Reestablished the position for the
corner at record bearing and distance from the 1964 accessories found as follows: 18" R.Pine S02W
30.5 links found in good condition, 10" W.Pine stump N24E 22 links.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
18" R.Pine S02°W 20.4' mrkd "SW1/16" (1964 BT)
7" Maple in clump S43°E 25.7' mrkd "SW1/16 BT"
9" Maple N78°E 41.95' do
NE Cor. of outhouse vault is N86°W 40.2'
E= 8120726.383 N= 214024.585



Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Coord. Ref.=NGS PID RJ0323: N= 208477.288 m. E= 8118424.098 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 06/27/2013

For the Michigan Department of Natural Resources, Forest Resources Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct. 1995