## SURVEY & REMONUMENTATION

APR 2 8 1995

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Nov 16 2 00 PM '94

or corners in COMMISSION (County)	Located In:	Corner Code ##		NANCY HAVILAND REGISTER OF DEEDS LIVINGSTON COUNTY, M 48843	ΙΙ
Public Land Survey	T _1N_ R _3E_ T R T R T R	H-13		-	
in Section S B. Miscellaneous S	T R T R		L.S.C.#339m Register of D	Deeds Stamp & File Number	
DARRELL, HUGHES, in a factor of the standard of survey instructions.  Journal of survey instructions of the standard of t	ield survey on	NOVEMBER 4, 1994.  The following state of 1970, the corner points mender uses therefore as required the interior. Bureau contraction of the Interior, Bureau contraction of the Interior of the Surveyors or by a Deci	2 6 3 4 7 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	C D E F G H I J K  5 - 4 - 3 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2	
expressed below:  NOTE: Not more than 4 corners,  on this certificate.  A. Description of original monum	all in the same town a	nd range, may be recorded	d 11 12 31 13	29 28 27 26 33 34 35 UNADILLA TWP-	-25 -36

White Oak 38" North 2½ degrees East 224 links White Oak 38" North 39½ degrees West 300 links

GLO: 1825 Sylvester Sibley, Deputy Surveyor

\*Additional historical information on back of sheet Description of corner evidence found and/or method applied in restoring or reestablishing corner:

> Corner not found. Re-establishment to be on a line between G-1, TlS, R3E and I-13, TlN, R3E at 2/3 the distance between F-13 and I-13, TlN, R3E. This method has the best fit for existing occupation and monumentation of the Michigan Base Line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-13, T1N, R3E, UNADILLA, established corner with 1-1/4" X 36" iron pipe, affixed with 2" dia. brass disk. Disk stamped "Livingston Co. 19834" and is accepted as a careful and faithful Monumentation Corner,

reestablishment of the position of the original corner.

19834

reestablishment of the position of the original corner.

195 DEG. 162.45' SET NAIL/TAG E/S 22" WILLOW.

180 DEG. 151' NORTH SHORE JOSLIN LAKE.

284 DEG. 45.42' SET NAIL/TAG S/S 36" MAPLE.

333 DEG. 59.74' SET NAIL/TAG SW/S 46" WILLOW.

CORNER FALLS AT S. END 40' EASEMENT, "SAN LURAY BEACH" SUB.

270 DEG. 28.95' FD. 1/2" IRON PIPE. 090 DEG. 11.00' FD. 3/4" IRON PIPE:

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED JAN., 1983

## H-13, SOUTH 1/4 CORNER SECTION 34, T1N, R3E, UNADILLA TWP.

CORNER NOT FOUND. NO EVIDENCE OF ANY SURVEYOR'S USE OF THIS CORNER. I HAVE DETERMINED THIS CORNER TO BE LOST. REESTABLISHMENT TO BE BY DISTANCE PRORATION BETWEEN F-13 AND I-13. EAST/WEST ALIGNMENT CONTROLLED BY PERPETUATED CORNERS F-1, G-1, AND I-13. E-1 AND H-1 NOT FOUND.

All the state of the second

1825 Sylvester Sibley, Deputy U.S. Surveyor, set corner at 40 chains from the East. P.7

1926 Grant Dunning plats "Unadilla Heights" L.2, P.80, ties into J-13, no tie or tag to any other section corner. P.8.

1958 John C. Miller plats "San Luray Beach", L.9, P.25, abutting west line of "Unadilla Heights", point of beginning is G-1 Lyndon Twp., Washtenaw Co. South line of subdivision is on a line from G-1 to the Southwest corner of "Unadilla Heights". (I find a deflection in the south line of the two subs.)

1960 Atwell Hicks survey shows measures from G-1 to I-1. ties in Joslyn Lake Road. Does not show Unadilla Twp. corners.

1987 Boss (Matt Brady) uses straight line from G-1 to I-13 for section break-down, P.9