

FILED

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

JUL 14 9 46 AM '95

For corners in
Livingston
(County)

Located in:

Corner Code #

NANCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI
48843

1. Public Land Survey T 4N R 4E F-13
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Section S _____ T _____ R _____

L.S.C. #417m

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2				
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Edward E. Anderson, in a field survey on June 27,, 19 95,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. notes dated June 20, 1823

G.L.O. witnesses Tamarac 6" N73°W 18 Lks

Tamarac 7" N35 1/2°E 20 Lks

Additional historical on back

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" rerod. Fitted witnesses by Benton, C.H.M.P., and Hughes

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-13 S 1/4 Cor. Sec.33 T4N-R4E

Set 36" x 1 1/4" Breakaway iron pipe with Brass cap (Liv. Co. Mon. Cor.)

5' north of centerline Allen Road

N48°E 35.42' Spike W/S 10" Poplar


S54°E 50.61' Spike N/S 18" Maple

S08°W 44.11' Spike E/S 20" Locust

S75°W 77.00' Spike N/S 18" Maple

Signed by E. Anderson

Surveyor's Michigan License No. 11495



Date July 5, 1995

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY
TEEN GROUP ON 4-5-95



EDWARD E. ANDERSON, P.S., P.E.
RICHARD F. FRANK, P.S.
BRIAN R. SHALTZ, C.S.T.

Members of:
Michigan Society of Professional Surveyors
American Congress on Surveying and Mapping
American Society of Civil Engineers

401 S. Leroy St.
Fenton, Michigan 48430-2164

(313) 629-8974
FAX (313) 629-9069

SUMMARY

March 23, 1995

^{CoR.}
F-13 SOUTH 1/4^A SECTION 33, T4N-R4E, COHOCTAH TOWNSHIP, LIVINGSTON COUNTY,
MICHIGAN

Found 1/2" rerod 5' north of the centerline of Allen Road (gravel)

Checked and measured to witnesses we found. Found 2 of 3 of Bentons witnesses and they checked, page 10 this dossier. Found 3 of 4 of C.H.M.P. witnesses and they checked, pages 11 and 12 this dossier. Found 3 of 4 of Hughes witnesses and they checked, page 17 this dossier. Found a capped iron (Mary Barnwell #33791) 128.43' east of the South 1/4 corner of said Section 33 and assumed it to be the North 1/4 corner of Section 4, T3N-R4E.

Distance from the South 1/4 corner to the S.W. corner of said Section 32 is 2650.11' on C.H.M.P. survey, Page 11 this dossier, and 2650.15' on Hughes surveys, pages 15 and 16 this dossier.

Distance from the South 1/4 corner to the S.E. corner of said Section 32 is 2650.18 on Bentons surveys, pages 8 and 9; and 2650.11' on Hughes surveys, pages 15 and 16 this dossier.

Made a clean sweep of immediate area and found no other corners or irons.

Gravel road running east and west. Roads flat in both directions.

Terrain is wooded in all directions. No occupation line to the north or south.

Not good location for G.P.S.

Came to the conclusion that the 1/2" rerod we found is the correct south 1/4 corner of said Section 33.

Edward E. Anderson
P.S.#11495

