CONTRACTOR OF	- <b>X</b>	i.
MEMONUMENTATION	<b>、</b> 、	1:
		FILED 9-
OCT 2 6 1995		
COMMISSION LAND CORNER RECORDATION ( Filing Requirement of Act 74, Mi	CT P.A 1970	· 15 12 03 PH '95
For corpore in	;;	NANCY HAVILAND ÉGISTER OF DELES
Livingston Located In: Corner Code #	Livi	
		48843
1. Public Land Survey  T  4N  R  6  C-12    -  T  R		
T R		
2. Property Controlling  S T R    in Section  S T R	L.S.C.# 43	3.5m
3. Miscellaneous S T R		
Property in Section S T R	Register of D	eeds Stamp & File Number
4. Lot No, Recorded Plat	A B	C D E F G H I J K L M
5. Private Claims		
	3	
	4	
I, <u>Edward Anderson</u> , in a field survey on <u>July 1],</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner point	9 <u>95</u> , 5	┾╼┼╌┼╼┼╶┟╼┼╶┤
in lines 1 and 2 above were in conformance with regulations and rules therefore as required	in the current	
manual of survey instructions of the United States Department of the Interior, Burn Management or by a decree of a Court of Law and/or that the corner points mentioned in I		
5 above were in conformance with the rules of the Michigan Board of Professional Surve Decree of a Court of Law; established, re-established, monumented, re-monumented, reco		┼╍┼╌┼╼┼╌┼╾┼╼╢╴
as expressed below:	10 30-	29
NOTE: Not more than 4 corners, all in the same town and range, may be recorde on this certificate.	ed 11 12 31-	
•	13	
A. Description of original monument and accessories and/or subsequent rest	oration:	
GLO NOTES DATED APRIL 5, 1823		:
GLO WITNESSES Oak 10" N47°E 38 Lks Oak 16" S29°W 84 Lks		
Additional tistanian data an taol		
Additional historical data on back	· · · · · · · · · · · · · · · · · · ·	
B. Description of corner evidence found and/or method applied in restoring of	r reestablishing corner:	
Found 1/2" rerod Fit witnesses, by Hughes, Ward an	d Albright	
found the follow fro michesses by hughes, hard an	Id ATH I GILL	
C. Description of monument for corner and accessories established to perpet	uate locating the position	of the corner:
C-12 W 1/4 COR SEC 32, T4N-R6E		
Set 1 1/4" x 36" iron pipe with Brass cap (	Liv. Co. Mon. Cor.	3' south
of fence running east and west		

1.1.1

ţ

N45°E 28.05' spike S/S 8" Poplar S53°E 57.59' spike N/S 24" Wild Cherry S74°W 42.15' spike E/S 14" Oak N11°E 40.60' spike W/S 8" Oak - 20 EOFMICHIG EDWARD E Date\_\_\_\_July 17, 1995 ANDERSON Signed by\_ С. 00 99 ENGINEER 11495 FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN, 1983 Surveyor's Michigan License No.\_\_ NO. 11495 Suneyors PA 245 1890, APPROVED BY LANGSTON COUNTY 6/1/95 m. JED 4 Passa GROUP CH.

ALPHA Land Surveying & Engineering, Inc.

401 S. Leroy St. Fenton, Michigan 48430-2164

n an

•

## SUMMARY

May 25, 1995

EDWARD E. AMUERSON, P.S., P.E. RICHARD F. FRANK, P.S. BRIAN R. SUALTZ, C.S.T.

Membrandian Society of Professional Mapping American Congress on Surveying and Mapping American Society of Civil Engineers

(313) 629-8974

FAX (313) 629-9069

by 246 1845 FLANDARD BATWARDELON COMMA

## C-12 WEST 1/4 CORNER SECTION 32, T4N-R6E, TYRONE TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN.

Found 1/2" rerod  $(1'^{\pm}$  deep),  $3'^{\pm}$  south of old wire fence running east and in line with old wire fence running to the north.

Found 2 of 3 of Grant Ward and Darrell Hughes witnesses and they checked, pages 11, 12, and 14 this dossier. Found 4 of 5 of Albright witnesses, and they checked, page 15 this dossier.

Distance from the West 1/4 corner to the N.W. corner of said Section 32 is 2659.00' on Garlock survey, page 8 this dossier, and 2659.07' on Hughes and Albright surveys, pages 13 and 15 this dossier.

Distance from the West 1/4 corner to the S.W. corner of said Section 32 is 2666.92' on Albright survey, page 9 this dossier, and 2665.21' on Grant Ward survey, pages 11 and 12 this dossier.

Made a clean sweep of immediate area and found no additional irons or corners.

Old fence line to the north and east. No other occupation.

Terrain is wooded north, south and east, and open to the west. Lake Shannon lies 40'- to the west.

Poor location for G.P.S.

С

Came to the conclusion that the 1/2" rerod we found is the correct West 1/4 corner of said Section 32.

Edward E. Anderson P.S.#11495

Architectural, Construction, Primerty and Drainage Surveys ingine - Land and Site \_\_ • Mortgage Ins in Reports

L -