## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RELIGIBLE STATION

## **Mackinac County Remonumentation Corner**

For corners in

Mackinac County

Located in:

Corner Code #

T41N R04W 1. Public Land Survey Т R R Ţ Т R T R 2. Property Controlling S S Т R in Section

S R Т

3. Miscellaneous Property in Sec.

S R

4. Lot No.

, Recorded Plat

5. Private Claims

I, Neil E. Hill, in a field survey on 12-20-99, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

| 1845 | GLO Notes A Burt  | 6" Tamarack<br>8" Tamarack                       | N 63 W<br>S 28 E                     | 17 lks<br>07 lks                     |
|------|---|--|--------------------------------------|--------------------------------------|
| 1995 | Gary Koepke<br>Fd 1" Iron in Mon Box,<br>witnesses, and checked<br>as part of M-123 resurfacing<br>Liber D Page 344 | 7" Tamarack<br>9" Cedar<br>6" Cedar<br>6" Spruce | N 50 E<br>S 10 E<br>S 25 W<br>N 45 W | 84.85'<br>69.36'<br>69.36'<br>80.45' |

No Subsequent Information

MAR 2 0 2000


Receivsechonled DIANE FRANKOVICH

MACKINAC COUNTY RECISTS. OF BEEDS

FEB 3 5 2000

图例 A. 1. 218[6]10]11[12]1[2[3]4[5]0

Register of Deeds Stamp & File Number



ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER P.A. 345 OF 1990 AT A MEETING HELD ON تد تخسلانکا

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1999 Fd 1" Iron In Monument box Accepted corner location

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 1" iron in monument box. Corner is 2.3' North of CL of M-123

8" Tamarack N 50 E 84.85' 9" Cedar 69.36' S 10 E 8" Cedar S 25 W 69.36 N 45 W 80.45 8" Spruce

Bearings are compass bearings, corrected for declination, all distances are to a double- head nail in the side of the s object unless otherwise noted.

Date

کرے ہو کر

2000 21 January

1472.5

Land

Surveyo

P. 0

Surveyor's Michigan Libense No. 27447

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983
REVISED OCT., 1995

1999-53