Cox 5. 4047

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T42 NR 10 Y

		Mackinac	COUNTY
DESCRIPTION OF CORNER	1/4 Section Corn	er between Sec. 18.	5-6
DESCRIPTION OF CORNER			
WITNESSES TO CORNER	5" Y. Pine	# 79 <sup>®</sup> E	105_links
	5" W. Pine	\$ 67° W	100 links
		-1/4 9 851	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 corner from one white pine B.T. (effaced) which was intended for 1/4 corner 45 links north of corrected 1/4 corner.

He evidence of B.T.s for this corner.

Placed cerner 45 links south of eld effaced 1/4 cerner. Found tamarack line tree at 29.60 chs. from twp. line north of here.

1/4 corner lies on 30' ridge ML-SW.

SURVEYORS SEAL

SIGNED BILLY D Suckles DATE 6/27/57