MAR 1 3 1998

MACKINAC COUNTY REMONUMENTATION CORNER

SECTION

LAND CORNER RECORDATION CERTIFICATE

SECTION		Filing Requireme	ent of Act 74	Mich PA 1	070						
For corners in		· ······g · · · · · · · · · · · · · · ·	on 017100 14, 1	, inchi: 1 '''''	310						
Mackinac (County)	Located In:	Corner (Code#							lj	
4. Dublin Land Commiss	-4 2	N _R 3W M	C M6/M7 #	4	,					(-) xeens	
1. Public Land Survey	T 42	TR Section 13				ř 1	iler e	9 1	aa-1		
	T 42	R S	ction 18	()	2.53		~~ £	J	. ,	EM	
2. December Controlling	T	_R	7	/			. فالمافد		istal	516 516	
2. Property Controlling in Section	S '	_ K			•	1 4	. 4 . 7 9 7	10 \$ 00 \$ 10.	4 " A " A	1	
3. Miscellaneous	S T	_ R					•				
Property in Sec.	s	_R	······································		F	Reaiste	r of De	eds Sta	amp &	File	Number
				L							
4. Lot No, Red 5. Private Claims	corded Plat			-	A	ВС	D E	F G	н	I J	K L
			······································		2		_	7			
					3	Ĭ	Ĭ	9	_ĭ_		
Neil E. Hill	in a field surve	ON DEC 22.1	907 do hereby s	state that under	4	-7-	_				12
requirements of P.A. 74, Mich	ilgan P.A. of 1970, the	corner points mention	ed in lines 1 and 2	above were in	5	i l					
conformance with regulations a United States Department of the	ne Interior, Bureau of La	ind Management or by	a decree of a Coun	of Law and for	6	10	17.	16	—15—	1.4	12
that the corner points mention	ied in lines 3, 4 and 5 a	bove were in conforma	ince with the rules o	of the Michigan	7	10			—15]	13
Board of Land Surveyors or recovered, found as expressed		unt of Law; establish	ed, re-established,	monumented,	8	19	-20	_21	22	23	24
NOTE: Not more than 2 a					9		ا	[1	
NOTE: Not more than 2 con this certificate,	omers, and the same	town and range, ma	ay be recorded		10	-30	_29_	_28	27	26	25
						Ĭ					
					11	31	_32	33.	34_	35	36
					13	Ĵ	Ĭ	Ĩ	Ĭ		l i
A. Description of original r	monument and acce	ssories and/or subs	equent restoratio	n:	13						
1840 GLO notes GLO disance	William Bu 2121.90' South		6" Aspen 7" Cedar								
No records of this con	ner being perpet	nated, however a	a survey by R	Bisler indi	cated	a pos	ition f	or this	s corr	er.	
B. Description of corner e	vidence found and/o	r method applied in	restoring or rees	stablishing cor	ner:						
	of corner. Set at on 466.20' furthe										
	•				š.	ACC	EPTED	BY THE	ЕМАС	Masar	S COUNT
	•		•			OUN	VEYPE	EM GM	uiii Pa.	STMS	~
						UFFI	JIAL (J	JRNER	HMDE	RPA	•
						HELD	วกาชย ION	ATA 0	MEE !	NG	
						•	*****	····		((
C Description of monumer	nt for corner and acc	eccorios actablisha	d to marmaturata la								
 C. Description of monumer Witness to point at lake 		essuirs estabiishe		MC ½" rer				nentet:	ion or	m	
8" Cedar N10W	63.44'	6" Cedar	N80E	07.97	OCT MT	en i ch	MULL	ıcınaı	ion ca	·P	
14" Cedar N20E	34.28'	14" Cedar	S45E	17.55'					336.23	e bei	Bulley
8" Cedar East	10.04'	8" Cedar	S30W	07.41'				a ^{rt}	1.12	1 11)	10/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/
8" Cedar S80E	16.93'	8" Cedar	Due West	08.29'				£C.		NEIL HILL	E
								(4) EP	<i>i</i> _	Land	
))	Survey No.	
									٥٠٠٠	27 44	
								**	W. C.P.	OLA	40 m
Signed by	Neil E.	12th PG		Date	F.174 .		Γ	ECE	MBE	R 22	, 1997
Surveyor's Michigan License	e No. <u>2744</u>	7									