

MAR 20 2000

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970
Mackinac County Remonumentation Corner

For corners in

Mackinac

Located In:

Corner Code #

1. Public Land Survey

T 43N R 10W

B-9

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, William L. Karr, in a field survey on July 13, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
(B-9) 1/4 Corner Common to Sections 19 & 30, Township 43 North, Range 10 West.
1849 William Ives, D.S. set post. Sugar 6 S55°E 16 Fir 12 N34°E 26
1979 Billy Buckler, P.S. 8887 (DNR) found a buried "T" iron 17 feet South of road centerline and recorded in Liber B, Page 170 of the Mackinac County Records
1993 Gary Koepke, P.S. 26458 (MDOT) found a "T" iron in monument box 20.46 feet Southerly of centerline U.S. 2 and recorded in Liber D, Page 191 of Mackinac County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
(B-9) 1/4 Corner Common to Sections 19 & 30, Township 43 North, Range 10 West.
Found "T" iron in monument box as described above. Accepted corner position as found. Corner was to be destroyed during road construction of U.S. 2 and was re-witnessed prior to construction.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
(B-9) 1/4 Corner Common to Sections 19 & 30, Township 43 North, Range 10 West.
After road construction set 1/2" iron with 3" stamped aluminum Mackinac County Remonumentation Corner cap in monument box.
Road stationing MDOT plans dated 7/21/97 is 28+043.83.

Witnesses:

Maple 11" N20°E 114.97 feet
Maple 10" S35°E 56.43 feet
Beech 11" S13°W 51.67 feet
Beech 13" N15°W 87.39 feet

ACCEPTED BY THE MACKINAC COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 11-05-99 NEH



Signed by William L. Karr Date 12/16/99

Surveyor's Michigan License No. 27450

NOTE: All bearings are compass bearings corrected for declination (6°W). All distances are to a nail and tag in the side of witness object unless otherwise noted.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 23, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

c:\wpdocs\cornerform\1999\mackinac\43nr10w.b-9

E - 0348