

1993

1993 Mackinac County Remonumentation Corner

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in

Mackinac

(County)

Located In:

Corner Code #

1. Public Land Survey

T 43N R 2W

E-3

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

RECEIVED & FILED
DIANE FRAP FOLIOCH
JACKSON COUNTY REGISTER OF DEEDS

OCT 28 1993

AM PM
7/8/9/10/11/12/13/14/15/16

Register of Deeds Stamp & File Number

I, David B. Guthrie, in a field survey on June 10, 1993,

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1845: Established By J.H. Mullett, G.L.O Survey. Set wood post and referenced:
4" Cedar - S31°E - 15 Lks/ 4" Birch - N44°W - 10 Lks.

1971: Survey by Mary C. Feindt.

1972: Survey by C. Eugene Ostling.

1987: Survey by Richard L. Hays of Nordlund & Assoc. for U.S. Forest Service.

- 1989

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993: Found a 2½" x 3' aluminum monument with a 3" aluminum cap stamped to identify the corner. This corner was set by Richard L. Hays in 1989 by double proportionate measurement between the North ¼ corner of Section 8, the Northeast corner of Section 9, the Northeast corner of Section 5 and the Southwest corner of Section 9. The corner was recorded by Richard L. Hays, P.S. No. 25847 on November 9, 1989. (Book D, page 43)

Plat of Survey Recorded as U.S. Gov't. Plat of Survey No. 14.

NOTE: Corners as placed by Feindt and Ostling were not accepted by Hays and the U.S. Forest Service.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993: N60°W - 6.34 feet - (R=6.35') - 8" Cedar
S46°W - 8.40 feet - (R=8.38') - 7" Spruce
N88°E - 10.51 feet - 8" Cedar
S32°E - 14.35 feet - (R=14.38') - 8" Cedar
North - 0.90 feet - Steel Post
S60°E - 39.30 feet - T-Iron by Feindt
S27°E - 152 feet - Wood Post and 1-1/2" Iron Pipe compatible with former Ostling references.

(Tree references are blazed and tagged.)

The monument is a 2½" x 3' aluminum monument with a 3" aluminum cap stamped to identify the corner.

Signed by

Date

Surveyor's Michigan License No. 22435

