

LIBER 061660023

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

B999636

For corners in

Macomb  
 (County)

Located In:  
Washington Twp.

Corner Code #

RECORDED IN MACOMB COUNTY  
 RECORDS AT 8:30 A.M.

DEC 28 1993

1. Public Land Survey

T 4 R 12

H-11

T \_\_\_\_\_ R \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling  
in Section

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous  
Property in Sec.

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

Register of Deeds Stamp &amp; File Number

I, Huston K. Kennedy, in a field survey on December 10, 1993,  
 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
 current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
 Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
 expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
 on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:  
 1817-GLO Wampler, D.S.; Set post; 9" Ash S02°W 14 Lns; 16" Ash N08°W 20 Lns  
 1973-Kobs, P.S. #14097; LCRC L.2360, Pg.808 - Fnd 1/2" Iron Rod in a monument box.  
 1973-Kobs, P.S. #14097; Survey L.2360, Pg.827 - Same wits as 1973 LCRC  
 1973-Kobs, P.S. #14097; Survey L.2370, Pg.385 - Same wits as 1973 LCRC  
 1990-Kobs, P.S. #14097; LCRC L.4924, Pg.674 - Fnd 1/2" Iron Rod in a monument box.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
 1993 Kennedy Surveying, Inc. - Kennedy, P.S. #17623 - Fnd 1/2" Iron Rod in a monument box without a cover located in the centerline  
 of 27 Mile Road, which is bituminous surface and 45' ± East of the M-53 overpass.

One witness point from the 1990 LCRC was found and it was used to recover and verify the found 1/2" Iron Rod in a monument box.

**ACCEPTED BY THE MACOMB COUNTY  
 SURVEY PEER GROUP AS THE OFFICIAL  
 CORNER UNDER MICHIGAN PUBLIC ACT 34  
 OF 1990 AT A MEETING HELD ON  
 12-15-93**

Frank J. DeDecker  
**FRANK J. DeDECKER, PS, PE, CHAIRMAN**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
 H-11 I replaced the found 1/2" Iron Rod in a monument box with a 3/4" x 24" Iron Rod w/2" diameter aluminum cap stamped "Macomb County  
 Monument MI Act 345 #17623" in a monument box.  
 N05°E-128.70'-Set PK Nail & Remon. tag in West face 15" Poplar (W/16" Poplar)  
 N47°E-41.95'-Set PK Nail & Remon. tag in South face Power Pole  
 S74°E-79.00'-Set PK Nail & Remon. tag in NE face Power Pole  
 S52°E-59.15'-Set PK Nail & Remon. tag in East face 60" Willow

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the  
 position of the original corner.

Signed by H.K.K.  
 Surveyor's Michigan License No. 17623

Date 12-10-93