

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Macomb</u> (County)	Located In:	Corner Code #
	<u>Ray Township</u>	
1. Public Land Survey	<u>T 4N R 13E</u>	<u>M5</u>
	<u>T</u> <u>R</u>	
	<u>T</u> <u>R</u>	
	<u>T</u> <u>R</u>	
2. Property Controlling in Section	<u>S</u> <u>T</u> <u>R</u>	
	<u>S</u> <u>T</u> <u>R</u>	
3. Miscellaneous Property in Sec.	<u>S</u> <u>T</u> <u>R</u>	
	<u>S</u> <u>T</u> <u>R</u>	

SURVEY &
REMONUMENTATION

FEB 27 1997

COMMISSION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Craig P. Amey, in a field survey on June 15, 1996 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1817	William Preston	Set post	GLO
1977	Herbert Kobs 14097	Found 1/2" iron	Cert of Survey L2811 P737
1977	Herbert Kobs 14097	Found 1/2" iron	LCRC L2811 P765
1978	Herbert Kobs 14097	Found 1/2" iron	Cert of Survey L3021 P153
1995	Donald King 30085	Found 1/2" iron	LCRC L6728 P628

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" iron with cap #19835 on a north and south tree line. Iron matched witnesses from LCRC L2811 P765 and LCRC L3021 P153.

North	2696.36'	East 1/4 corner of section 12, 40 chains or 2640' GLO, 2684.42' prorated
South	2678.58'	East 1/4 corner of section 13, 40 chains or 2640' GLO, 2678.11' prorated

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced existing found iron with a 3/4" by 24" rebar with a 2" diameter aluminum cap stamped "Macomb County Monument MI ACT 345 M5 34970"

270° 11.50'	Set PK and Macomb County Remonumentation tag below a found PK in the N face of a 15" Apple
204° 14.31'	Set PK and Macomb County Remonumentation tag above a found PK in the E face of a 16" Box Elder
66° 60.75'	SE corner of house #25010
344° 52.23'	Set PK and Macomb County Remonumentation tag above a found PK in the E face of a 23" twin Box Elder
0° 117.03'	Set 3/4" by 24" rebar with a 2" diameter aluminum cap (A5, T4N, R14E)

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

ACCEPTED BY THE MACOMB COUNTY SURVEY PEER
GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN
PUBLIC ACT 345 OF 1990 AT A MEETING HELD
ON 9-17-96

William E. Soderberg
WILLIAM E. SODERBERG, P.S., CHAIRMAN

Signed by Craig P. Amey Date November 30, 1996

Surveyor's Michigan License No. 34970

