

MAR 16 1998

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SECTION
MASON (County)

Located In:

Corner Code #

1. Public Land Survey

T 18 NR 16 W

G - 13

2. Property Controlling in Section

S

T

R

3. Miscellaneous

S

T

R

Property in Sec.

S

T

R

4. Lot No. , Recorded Plat

5. Private Claims

I, Sammy S. Barnett, in a field survey on Sept. 15th 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G - 13 Corner common to sections 33 & 34 T187N, R16W

1838 GLO survey by Mullett & Brookfield

Set post

1 Hem. 12" N25E 34 lks (22.44')

2 Hem. 14" N35W 30 lks (19.8')

1879 survey by J.H. Jones

Mon. not given

Identified by old trees

recently cut down

No witnesses

1886 survey by Metcalf, Mon not given
Used Griswolds stake, no witnesses

1979 Mason Co. Rd. Comm. by J. Borsfay
Found 1/2" bolt with small rocks raised
with 3/4" re-bar in Mon. box.

3 1" iron East 9.23'

4 P.P. NW 70.3'

5 Maple 17" NE 83.97'

6 P.P. NE 59.15'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G - 13 Corner common to sections 33 & 34 T187N, R16W

On Sept. 15th 1997, I found a 3/4" x 12" rebar in an existing monument box, the condition of the witnesses is as follows,

1 Gone # 2 Gone # 3 Found # 4 Gone # 5 Gone # 6 Gone

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G - 13 Corner common to sections 33 & 34 T187N, R16W

On Sept 15th 1997, I replaced the found 3/4" rebar with a Standard Mason County Monument and accepted this location as the best available evidence of the position of the original corner, and took the following witnesses.

7 Maple 24" N34E 66.51' set 60d spike in SE side

8 Power pole # 79E1 N72E 59.00' set PK nail in SE side

9 Guy pole S31E 65.11' set PK nail in SW side

10 Power pole # 79 S53W 47.51' set PK nail in NW side

11 Standard Mason Co., Mon. East 9.26' (cor. common to sections 3 & 4 T17N, R16W) (# 3)

Corner is in a monument box.

Signed by Sammy S. Barnett

Date 11-4-97

Surveyor's Michigan License No. P S # 16923

Peer Group Reviewed

and Approved

Date: Oct. 2, 1997

Kenneth L. Ross

Mason County Surveyor