

DEC 29 1998

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

MASON

(County)

Located in:

Corner Code #

1. Public Land Survey

T 18N R 16W

I-5

2. Property Controlling
in Section

S

T R

3. Miscellaneous
Property in Sec.

S

T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Kenneth L. Ross, in a field survey on August 25 1998, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-5 Section Corner for Sections 10, 11, 14 and 15, T18N-R16W.

1836, Sylvester Sibley, G.L.O.

Set Wood Post

#1 Beech 8" S 48 E 10 lks. (6.60')

#2 Beech 6" N 31 W 15 lks. (9.50')

1976, Ken Ross, RLS #17634

Found existing 5/8" Iron in the C-L of Road,

#3 Power Pole N 20 E 71.57'

(file no. E-88)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-5 Section Corner for Sections 10, 11, 14 and 15, T18N-R16W.

On August 25, 1998, I found 1 1/4" drift pin, 18" long, 3 feet South of the center-line of Johnson road, drift pin was next to Stone. I found no evidence to dispute this location for the corner.

Condition of record witnesses are as follows: #1 Gone #2 Gone #3 Found in good condition

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-5 Section Corner for Sections 10, 11, 14 and 15, T18N-R16W.

I replaced 1 1/4" drift pin, in the exact location with a 5/8" Re-rod, 24" long, with an aluminum cap, stamped MASON COUNTY MONUMENT, set 0.5 feet below gravel road. This corner is accepted as a careful and faithful re-establishment of the position of the original corner.

ext. "BT" #3 Power Pole N 20 E 71.18' (set P.K. nail in SE side of pole)

new "BT" #4 Steel Post culvert marker N 10 W 43.34' (center of post)

new "BT" #5 Elm 4" S 12 W 62.55' (60d spike in SE side of tree)

new "BT" #6 Steel Fence Post S 13 E 73.81' (center of post)

Note: I measured reference distances from I-5 to I-6 at 2650.06 feet. & from I-5 to H-3 at 2650.25 feet.

Signed by

Ken Ross

Date

Sept. 2, 1998

Surveyor's Michigan License No.

17634

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN. 1983

ADAPTED FOR WORD PROCESSING MARCH 1993

17634