

FEB 08 2000

## SECTION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners In: Located In: Corner Code #  
Mason County

1. Public Land Survey T 19N R 16W D-13  
T R  
T R  
T R  
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R  
4. Lot No. , Recorded Plat  
5. Private Claims

FILED  
AT 10:42 O'CLOCK A. M.  
NOV 10 1999  
MARGARET KOLASKI ELLIOTT  
MASON COUNTY  
REGISTER OF DEEDS  
Register of Deeds Stamp & File Number

I, Kenneth L. Ross, in a field survey on September 11, 1999, Do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

## A. Description of original monument and accessories and/or subsequent restoration:

S ¼ Corner Section 32, T.19N., R.16W.,

GLO Mullett and Brookfield, 1838

"Set quarter Section post"

(1) Beech, 6", S41°W, 36 links (23.76')

(2) Hemlock, 18", N60°E, 31 links, (20.46')

R.O. Towns, 1903, Book 2, page 184

"Stone for Corner" No Witnesses Given

Distance West to C-13, 2630.76'

Distance East to E-13, 2622.84'

K.L. Ross, Drain Survey

Tied this corner "existing iron"

No Witnesses Given.

Distance East to E-13, 2629.62'

Peter Eastman, 1876, Book 1, page 26 &amp; 27

Does not state what he found,

No Witnesses Given.

Distance West to C-13, 2627.46'

Distance East to E-13, 2603.04'

K.L. Ross, 1984, Act 132, Liber 314,

page 482, "Existing Iron"

No Witnesses Given

Distance East to F-13, 5259.10'

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

S ¼ Corner Section 32, T.19N., R.16W.,

I found a 5/8" X 24" epoxy coated re-rod, 2' South and 1' below the surface of the center-line of Decker Road. Witnesses (1) and (2) have been destroyed. I found no other evidence to dispute the location of this corner.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

S ¼ Corner Section 32, T.19N., R.16W.,

I replaced the 5/8" epoxy coated re-rod in the exact location with a Standard 3" Cast Iron Harrison Monument stamped "Mason County Monument" 2 foot South and 1 foot below the surface of the center-line of Decker Road. This corner accepted as the best available evidence of the re-establishment of the position of the original corner.

(3) D-1, T.18N., R.16W., Set 3" Harrison Cast Iron Monument, East, 34.15'

(4) Set 60d spike West side of P.P. N12°E, 46.73'

(5) Existing 60d spike East side of P.P. S18°E, 26.77'

(6) There is nothing else to witness this corner to so I re-measured the Distance East to E-13, 2629.60'

Field Line to the North

Center-line of Two Track Field Drive to South, East 13 feet

Signed by Kenneth L. Ross Date Nov. 4, 1999

Surveyor's Michigan License No. 17634

Approved by Peer Review Group on Nov. 4, 1999  
Kenneth L. Ross, County Representative Kenneth L. Ross

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
ADAPTED FOR WORD PROCESSING MARCH, 1983

LIBER

4 PAGE 306

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

