

SURVEY & REMONUMENTATION

MAY 07 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MASON

(County)

Located in:

Corner Code #

1. Public Land Survey

T 20N R 15W

G-11

2. Property Controlling
In Section

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

4. Lot No. , Recorded Plat

5. Private Claims

FILED

AT 11:53 O'CLOCK a M

AUG 14 1996

MARY GOLDEN KOLASKI
MASON COUNTY
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Sammy S. Barnett, in a field survey on July 23, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		10		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

G-11 Section Corner for Sections 28, 27 33 and 34, T20N, R15W.

1839, John Brink, G.L.O.

Set Wood Post

#1 W. Pine 11" N68°E 201ks.(13.20')

#2 Y. Pine 13" S34°W 191ks.(12.54')

1975, Ken Ross, #17634,

Set 1/2" Re-rod @ Road intersections

#3 Tw. Cherry 10" S70°E 58.52'

#4 Post USFS Trail #5528

S80°E 73.78'

1976, M.C.R.C.

found 1/2" Re-rod

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-11 Section Corner for Section 27, 28, 33 and 34, T20N, R15W.

On July 23, I found a 1/2" Re-Rod with RLS cap #17634, at the intersection of of five Trail roads 0.5 foot below road surface(dirt), I found no evidence to dispute this location for the corner.

Condition of recorded witnesses are;

#1 Gone

#2 Gone

#3 Gone

#4 Found 1" squ. Steel post

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-11 Section Corner for Sections 27, 28, 33 and 34, T20N, R15W.

I replaced 1/2" Re-rod, in the exact location, with a Standard Mason County Monument, set 1.0 foot below road surface, and is accepted as a careful and faithful reestablishment of the position of the original corner.

White Pine 6" S 76° W 47.05'(60d spike in NW side of tree)

Red Pine 18" N 47° W 70.75'(60d spike in NW side of tree)

Tri. Maple 6"-6"-5" N 24° E 67.35'(60d spike in SE side of tree)

White Oak 9" S 52° E 110.10'(60d spike in SW side of tree)

Signed by

Sammy S. Barnett

Date

8-17-96

Surveyor's Michigan License No.

14923

Peer Group Reviewed

and Approved

Date:

8-13-96

Kenneth L. Ross

Mason County Surveyor

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1995



LIBER

4 PAGE

24