

SURVEY & REMONUMENTATION

MAY 07 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MASON
(County)

Located In:

Corner Code #

1. Public Land Survey

T20N R17W

M-01 WITNESS COR
S. SIDE OF LAKE

2. Property Controlling
in Section

S T R

T R

#1

3. Miscellaneous
Property in Sec.

S T R

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Sammy S. Barnett, in a field survey on July 26, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-01 Witness to the Section Corner for NE Corner Section 1, T20N, R17W, South side of Shingle Mill Lake)

1837, Mullett & Brookfield, G.L.B.

Set Wood Post

#1 Hemlock 12" S43°W 191ks.(12.54')

#2 Hemlock 8" S39°E 51ks.(3.30')

1974, John Radcliffe, #11368

Set Iron & Cap proportionately on line

#3 Oak 10" N08°W 54.09'

#4 Tw. W. Pine 14" S77°E 56.50'

#5 W. Pine 16" S42°E 48.60'

1993, Ken Ross, #17634

Re-set from witness

2" x 60" Iron Pipe

#6 B. Oak 16" S25°W 25.92'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-01 Witness to the Section Corner for NE Corner Section 1, T20N, R17W, South side of Shingle Mill Lake

On July 26, I found a 2" Iron pipe, 1½ feet above the ground at edge of Shingle Mill Lake, pipe is full with concrete with a RLS cap inside (#17634 Ross), I could not find Radcliffes corner or any of his witness I found no evidence to dispute this location for the corner.

Condition of recorded witnesses are;

#1 Gone

#5 did not find

#2 Gone

#6 Found in good condition

#3 did not find

#4 did not find

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-01 Witness Corner to the Section Corner for NE Corner Section 1, T20N, R17W, South side of Shingle mill Lake

I accepted 2" x 60" Iron Pipe as a substantial marker for the Corner, and is accepted as a careful and faithful reestablishment of the position of the original corner.

(ext. BT #6) Black Oak 18" S 25° W 25.92'(60d spike in NE side of tree)

White Oak 13" S 46° E 105.28'(60d spike in South side of tree)

Red oak 5" S 78° W 59.95'(60d spike in SE side of tree)

Red Oak 6" N 50° W 75.37'(60d spike in north side of tree)

Signed by

Surveyor's Michigan License No.

Date 9-28-96

Peer Group Reviewed
and Approved

Date: 9-30-96

Kenneth L. Ross
Mason County Surveyor

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 2

REVISED MAY
REVISED JAN
REVISED OCT

LIBER

4 PAGE

11

FILED	
AT 9:18	O'CLOCK a N
OCT - 3 1996	
MARY GOLDEN KOLASKI MASON COUNTY REGISTER OF DEEDS	
Register of Deeds Stamp & File Numt	

	A	B	C	D	E	F	G	H	I	J	K
1											
2	6			5		4		3		2	
3											
4	7			8		9		10		11	
5											
6	18			17		16		15		14	
7											
8	19			20		21		22		23	
9											
10	30			29		28		27		26	
11											
12	31			32		33		34		35	
13											

