REMONUMENT

MECOSTA COUNTY REMONUMENTATION PROGRAM

MAY 0.5 1997

CORNER APPROVED BY PEER GROUP ON October 24, 1996

	LA	ND CORNE	R RECORDATI	ON CERTIFICATE	=			
COMMIS	Sister Fil	ling Require	ement of Act 74	l, Mich. P.A. 1970		TATE DE MIC	BIGAN	
For corners in Mecosta (County)	_ Located In Colfax Tov	-	Corner Code #		STATE OF MICHIGAN COUNTY OF MECUSTA RECEIVED FOR RECORU			
		· •	n 0		'96	DEC 17	A11:31	
Property Controlling in Section Miscellaneous	SEC 28 T 15N R T R T R S T R S T R S T R		E-9	Reg	•	raane /3 IEGISTER OF Stamp & F	DEEDS	er
Property in Sec.	STR		·		A R C D	E F G		
do hereby certify that under in lines 1 and 2 above were current manual of survey ins Management or by a decrate above were in conformance to Court of Law; established expressed below: NOTE: Not more than on this certification.	r , in a fix requirements of P.A. 74, e in conformance with re- tructions of the United S of a Court of Law and/or with the rules of the Mich i, re-established, monu- 4 corners, all in the ate. hai monument and acc	eld survey on	June 26, f 1970, the corner por rules therefore as a not of the Interior, Be obtines mentioned in it Land Surveyors or be numented, recover- and range, may be for subsequent re-	ints mentioned required in the urreau of Land nes 3, 4 and 5 ya Decree of a ed, found as e recorded	2 6 5 3 4 7 8 5 6 18 17 7 8 19 20 9 10 30 29 11 12 31 32	21 28 2	3 2 10 11 22 23 27 26	
Beech N70°W 25 1895 Lyman W. June, C August 30, 1979 James	links = 16.50' ounty Surveyor "wi G. Knapp RLS #258	24" Pine S th sleigh sh 53 (Survey)	27°W 19 links = noc & stump fen L10 P772) "Foun	12.54'	# ≈ 33.0′			
May 6, 1980 James G. 1 stump fence Ea		LCRC L2 P12)	"Found 1/2"x	2-1/2" iron in ce 33.20' Set nail				
June 19, 1984 James G	•	•	-					
February 24, 1987 Hen	ry J. Mulder RLS #	25862, Unred	corded Survey.	No Witnesses giv	en			
	. Keller RLS #1069 side 6" Cherry N25 side 24" Maple N77	5°E 71.69'	Corner Teleph	3" deep in C/L" 1 one Box \$87°E 30. 853 in Fence Post	05'	line Stum	p fence l	Bast
July 10, 1991 Gerald . Plow beam end 30" Maple 837" Fence Post 845	Reinforcing ro	od N27°E 14.0 ne Post 820°	00' Pr 50.60'		witness appea or another co		ž	
B. Description of corne	er evidence found and	or method ap	pplied in restoring	or reestablishing co	mer.			
Set 60d East s Found 30d West Found 30d Nort	. Keller RLS #1069; the tile. Found s side 32" Oak N10°E cerly side 6" Cherr ch side 24" Maple N 53 North side Corn	leigh shoe 231.39' Ty clump N25 177°E 33.36'	1' long 0.25' d °E 71.45'	keep and 0.4' Sou	th of the cen	ter of tile		y the
C. Description of monu	iment for corner and a	accessories e	stablished to perp	etuate locating the p	position of the c	orner:		
Accepted Clay Tile and original corne		ion Monument	as a careful :	and faithful perp	etuation of t	he positio	n of the	
Set 60d and ta Set 60d and ta	g E. side 32" Oak g W. side 6" Cherz g N. side 24" Hapl g above tag #25853	y Clump N23 6 N77°B 33	°E 71.53′ .28'	: (leaning NE) in	stump fence 1	Sast. 8891	SF Mich	

Surveyor's Michigan License No. 10693 SEPROVED BY MECHETA CO. PEER GROUP FORWARD BY MECHETA CO. PEER GROUP F

LIRER 100 PACE

Date November 22, 1996

107 LAND





