P.A. 345 OF 1990
MIDLAND COUNTY

JAN 2 1 1999

0/10/0	18 010
2////	0416

REMON. COR. M-13, INGERSOLL TWP.

LAND CORNER RECORDATION CERTIFICATS ECTION

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Midland	,	393	
(County)	Located in:	Corner Code #	
1. Public Land Survey	T <u>13N</u> R <u>2E</u> T R T R	<u>M-13</u>	STATE OF MICHIGAN MIDLAND COUNTY REMONUMENTATION & FILED
2. Property Controlling	s T R		12/16/1998 12:11:56 PM
in Section 3. Miscellaneous Property in Sec.	S T R S T R		BEVERLY J. THAYER REGISTER OF DEEDS Register of Deeds Stamp & File Number
4. Lot No, Records 5. Private Claims	ed Plat		

I, <u>RODNEY CLAYPOOL</u>, in a field survey on <u>APRIL 25</u>, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

ABCDEFGHIJKLM 2 3 4 10 11 5 6 18 16 İs 7 8 19 Ż2 23 9 10 29 28 26 11 12 32 4 35 13

- A. Description of original monument and accessories and/or subsequent restoration:
- M-13 Corner common to Section 36, T13N-R2E; Section 31, T13N-R3E; Section 1, T12N-R2E; and Section 6, T12N-R3E

Gio survey, 1830's, set post Survey by J. Schafer, 1977, found 3/4" pipe raised with 1/2" rod; 1978, found 1/2" rod

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee and is on file at the Register of Deeds Office.



- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- M-13 Corner common to Section 36, T13N-R2E; Section 31, T13N-R3E; Section 1, T12N-R2E; and Section 6, T12N-R3E

Found 3/4" pipe in mon box per surveys by J. Schafer

Corner M-13 was approved for remonumentation at a Peer Review Committee Meeting on August 17, 1998.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- M-13 Corner common to Section 36, T13N-R2E; Section 31, T13N-R3E; Section 1, T12N-R2E; and Section 6, T12N-R3E

Found 3/4" pipe in mon box per surveys by J. Schafer, set brass cap in 3/4" pipe stamped Midland Co.Remon Cor. PS 29241, and is accepted as the best available evidence of the position of the accepted corner.

N 45 Deg W, 40.40', nail and disc in power pole S 45 Deg W, 48.17', pk nail and disc in guy pole S 45 Deg E, 45.89', nail and plastic disc in power pole N 45 Deg E, 45.68', nail and plastic disc in guy pole

Signed by Roding	0	Clarand
	-	

Date 09-11-98

Surveyor's Michigan License No. 29241

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971 Revised May 14, 1971

Revised Jan., 1983