BLIAVEY & REMONUMENTATION

FEB 23 2001

REMON. COR. E-5, INGERSOLL TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

521

STATE OF KICHIGAN HIDLAND COUNTY REMONUMENTATION & FILED

12/28/2000 8:44:27 AM

SCOTT I. HAINES REGISTER OF DEEDS

SEC	TION
-----	------

For corners in Comer Code # Midland Located in: (County) T <u>13N</u> R <u>2</u>E 1. Public Land Survey R 2. Property Controlling in Section

Property in Sec. , Recorded Plat 4. Lot No. 5. Private Claims

Miscellaneous

I, RODNEY CLAYPOOL, in a field survey on June 15., 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on that under requirements of the conformance with regulations and rules therefore as required ines 1 and 2 above were in conformance with regulations and rules inererore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered found as expressed below: monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number					
Register of D	3609 000				
A · B	C D E	F G	H: 1	JK	L M
	777			ŢŢ	
2 - 6	<u>+</u> 5 +	4 +	· > 十		' ']
3	╂┉╂╌┤		-+-+		
4 - 7	+ 8 +	9 †	- 10 T	11 1	12
5	┼╌┼╾╋				12
6 - 18	+ 17 +	- 16	- 15 †	14 7	15
,	╌┼╼┧				
8 19	+ 20 +	21 1	22	23	24
9				~~~	25
10 F 30	+ 29-	 28 -	27-	- 26 -	25
11		 	34 -	35 -	36
12 - 31	+ 32 -	 33 -	† 24-		لثا
13				A	

- A. Description of original monument and accessories and/or subsequent restoration:
- Corner common to Sections 8, 9, 16 and 17 E-5

Survey by Gio, 1030 s, set post Survey by D. Whittier, 1989, 1970, 1972, set ½° pipe in monument box, proportional measurement N&S – E&W Survey by J. Schafer, 1978, monument box

Survey by E. Goss, 1980, monument box

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.
- Corner common to Sections 8, 9, 16 and 17 F-5

Found % pipe in monument box per surveys D. Whittier, J. Schafer and E. Goss.

1969 proration does not fit GLO, but does fit occupation



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- Corner common to Sections 8, 9, 16 and 17 E-5

Replaced pipe with 5/8" rod and brass cap stamped Midland Co. Remon Cor PS 29241 and is accepted as the best available evidence of the position of the accepted corner.

S 45 Deg E. 57.61, Northeast corner building (Rec. 57.55) N 35 Deg E, 48.03, railroad spike in power pole (Rec. 48.17 to tag)

S 45 Deg W, 43.52, nail and disc in guypole (Rec. 43.65)

N 60 Deg E, 58.96, nail and plastic disc in siren pole

West, 2.5', centerline N-S road

Date 12-26-00 Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971 Revised May 14, 1971 Revised Jan., 1983 Signed by Surveyor's Michigan License No. 29

> ASPROYED LAND CORNER P.A. 345 OF 1990 MIOLAND COUNTY 12/27/00 999