## **SURVEY &**

REMONUMENTATION REMON. COR. F.S, INGERSOLL TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 FEB 2 3 2001

STATE OF MICHIGAN KIDLAND COUNTY REMONUMENTATION & FILED

12/28/2000 8:44:27 AM


SCOTT 1. HAINES REGISTER OF DEEDS

Register of Deeds Stamp & File Number

| For corners in Midland   | SECTION   | Located in:  | Comer Code #  |
|--|---|--|---|
| (County)   |   |  | F-5   |
| 1. Public Land Su  | rvey  | T 13N R 2E<br>TR<br>TR<br>TR   |   |
| Property Control     in Section     Miscellaneous     Property in Section            | s S<br>ec.  | TR<br>TR<br>TR   |   |
|  | , Recorded Plat   |  |   |
| E Private Ciani  | 13  |  | hereby certify  |
| I, RODNEY CLAYP<br>that under requirem<br>lines 1 and 2 above<br>in the current many | OOL, in a field survey of ents of P.A. 74, Michiga were in conformance wall of survey instruction and Management or business. | in June 15, 2000, out in P.A. of 1970, the cor with regulations and rulins of the United State y a decree of a Court | nereby certify mer points mentioned on es therefore as required es Department of the of Law and/or that the formance with the rules |

in the current manual or survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.



OF BICHIO

RODMEY D. CLAYPOOL

ROYEVAN

Min

- A. Description of original monument and accessories and/or subsequent restoration:
- 1/4 Corner common to Sections 9 and 16 F-5

Survey by Glo, 1830, set post Survey by D. Whittier, 1969 Survey by Hunter-Whittier, 1970, set 3/2" pipe

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 1/2 Corner common to Sections 9 and 16

Found % pipe per surveys by Hunter and Whittier. This fits occupation line to North and South

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- F-5

Replaced pipe with 5/8° rod and brass cap stamped Midland Co. Remon Cor PS 29241 in monument box and is accepted as the best 1/4 Corner common to Sections 9 and 16 available evidence of the position of the accepted corner.

N 10 Deg W, 23.2', centerline West end 12" CMP N 45 Deg E, 31.47, chiseled "+" in East end 12" CMP S 60 Deg E, 40.61, notch in East end 36" CMP S 40 Deg M/ 35 50, potch in West and 36" CMP

S 40 Deg W, 25.50, notch in West end 36" CMP

Signed by Surveyor's Michigan License No.

12-26-00 Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971 Revised May 14, 1971 Revised Jan., 1983

APPROVED LAND CORNER P.A. 345 OF 199J MIDLA: D COUNTY

12/27/00/19