

REMON. COR. M-2, MIDLAND TWP.
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

510

For corners in
Midland

(County)

Located in: Corner Code #

1. Public Land Survey

T 14N R 2E M-2

T R

T R

T R

2. Property Controlling
in Section

S T R SURVEY &

S T R REMONUMENTATION

3. Miscellaneous
Property in Sec.

S T R FEB 23 2001

S T R

4. Lot No. , Recorded Plat SECTION

5. Private Claims

I, RODNEY CLAYPOOL, in a field survey on July 24, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

STATE OF MICHIGAN
MIDLAND COUNTY
REMONUMENTATION & FILED

12/28/2000 8:44:27 AM

SCOTT I. HAINES
REGISTER OF DEEDS


Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

M-2 Corner common to Section 1, T14N-R2E (M-2) and Section 6, T14N-R3E

Survey by Glo, 1830's, set post
Survey by Edmands Engineering, 1972, found nail
Survey by Ayres Associates, 1985, found 1/2" rebar
Bay Co. LCRC by J. Jones, 1999, set Bay Co. Remon corner (L-004, P-289)



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-2 Corner common to Section 1, T14N-R2E (M-2) and Section 6, T14N-R3E

Found rod and brass cap per surveys by Edmands Engineering, Ayres Associates and LCRC by J. Jones.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-2 Corner common to Section 1, T14N-R2E (M-2) and Section 6, T14N-R3E

Found 5/8" rod and brass cap stamped Bay Co. Remonumentation PS 19838 and set mon box and is accepted as the best available evidence of the position of the accepted corner.

N 20 Deg W, 117.08', nail and B.C. Disc in 6" Ash
N 80 Deg W, 50.61', nail and B.C. Disc in 4" Cherry
N 80 Deg E, 43.7', centerline stop sign post
S 45 Deg E, 31.40', mag nail in concrete bag headwall
On centerline N and S Road
On centerline road to East
10' ± South of tree line to West

Signed by Rodney D. Claypool
Surveyor's Michigan License No. 29241

Date 12-12-00

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1971
Revised Jan., 1983

APPROVED LAND CORNER
P.A. 345 OF 1980
MIDLAND COUNTY

12/31/00