L. C00004, P. 00297

9/11/18

Land Corner Recordation Certificate

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Craig W. McVean				Field Survey Date: January 18, 2018								
For corner(s) in:	Midland			County	_							
Original Public	Corner Code											
s	T	F	₹									
s	Т	F	}		. A	В (C D I	E F (G H	IJŀ	< L I	Μ.
S	Т	F	}	•	~ 1 _[:		1			71
s	ТТ	F	?		2	6 :	5	4	- 3	2	1	2
Property Controlling Corner				Corner Code	3	.	Á	9	- 10	- 11	12	- 3 4
S	Т	F	}		- 5	• • • • • • • • • • • • • • • • • • •	Ţ		۹			5
S	ΤΤ	F	}		- 1	40		40	4 '=		46	
S	Т	F	₹		- 6	18	- 17 -	16	15	- 14 -	13	6
S	T	F	\	***************************************	7						-	7
Property Corner				Corner Code	8 9	19	20	21	22	23	24	8
S 10) T	14N F	2W	. 5	. 10	30	29	28	27	26	25	10
S	. Т	F	₹		_ 11	-,-						- 11
S	Т	F	{		- 12	31	- 32 -	33	- 34 -	2.5	36	
S	T	F	}			· 5/1 · ·	32	33	. 54 .	- 50	30	
Protracted Public Land Survey Corner				Corner Code	-13 <u>/</u>	В (DI	= F (ЗН	IJŀ	< L 1	վ13 М
S10)T	14N F	2W	H4	_							
S	Τ	F	₹		_							
S	Т	F	}									
S	T	F										•

Part A: Corner History

<u>H4</u> – C ¼ Corner Sec. 10, T14N, R2W - None

<u>5</u> – CN 1/16 Corner Sec. 10, T14N, R2W - None

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

- H4 C 1/4 Corner Sec. 10, T14N, R2W -Set stamped 2" Aluminum Cap on 5/8" x 34" long iron rebar at intersection of 1/4 lines per standard BLM procedure. The center of a 10" steel pipe fence corner is N80°24'W 21.5'. The fence is mostly standing barb wire to the West and South. 1/4 mile south the fence is 10'± West of the N-S 1/4 line. Traced the fence West 1317'± (1338' from 'H4') and a 10" steel pipe fence corner is 30' North of the E-W 1/4 line. The fence is standing to the E & S at this point. The fence remains that continues west is barb wire on the ground and wire in some trees. At 2364' west of 'H4' the fence remains are 50'± North of the E-W 1/4 line. The fence remains then bend and proceeds to arc to a fallen RR tie corner post near the East ROW of Geneva Road some 32' North of the E-W 1/4 line and 32' East of the West section line. The grid distance from 'H4' to 'G4' is 2654.44'. Thus it was concluded that the fence did not represent a valid location of the E-W 1/4 line in Section 10.
- <u>5</u> CN 1/16 Corner Sec. 10, T14N, R2W -Set stamped 2" Aluminum Cap on 5/8" x 34" long iron rebar per standard BLM procedure.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

- H4 C ¼ Corner Sec. 10, T14N, R2W -Stamped 2" Aluminum Cap on 5/8" x 34" long iron rebar. Set Blue Composite Post with Loc. tag 1' NE. N55°W 50.05' to set N & T in SW side 18" W. Pine North 26.87' to set N & T in E. side 7" W. Pine N88°E 10.21' to set N & T in S. side 11" Oak S48°W 26.36' to set N & T in SE side 10" W. Oak
- Stamped 2" Aluminum Cap on 5/8" x 34" long iron rebar.

 Set Blue Composite Post with loc. tag 1' SE
 East 3.12' to set N & T in N. side 7" R. Maple
 S43°E 32.39' to set N & T in SW side 24" W. Pine
 N86°W 18.93' to set N & T in N. side 5" R. Maple
 N43°E 16.59' to set N & T in NW side 6" Oak

5 - CN 1/16 Corner Sec. 10, T14N, R2W -



Craig W. McVean

Professional Surveyor's License No.: 39088

Prepared By: Craig W. McVean Michigan Dept. of Natural Resources 8015 Mackinaw Trail Cadillac, Michigan 49601