APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

SURVEY & --REMONUMENTATION

MIDLAND COUNTY REMONUMENTATION

FEB 2 4 1998

8/01/97	SIT
For corners in	

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

365

MIDLAND (County)	Located In:	Corner Code #	
1. Public Land Survey	T <u>14N</u> R <u>2W</u> TR TR	A-8	
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR S TR		

STATE OF MICHIGAN HIDLAND COUNTY FILED EMONVINEN TATION 11 DEC 97 12:04 P.M.

BEVERLY J THAYER REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. LOI NO,	, Recorded Plat
5. Private Claims	

I. MARK R. ROBISON in a field survey on July 1 requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the , 19 97 do hereby state that under United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

1 A B	CD	E F	G H	ΙJ	KLM
2 - 6-]	
3			\perp \downarrow	<u> </u>	
4 - 7-	┼-╽-	<u></u>	10_	11-	12-
5 —		 	┼-├-		
6 - 1 8	17-	16	15	 	13-
7	 	 	╂┈├─	-	++
8 - 19 -	2'0 	21	22_	23-	-24-
9					╂╌╂╾┨
10 -30-	29 	28 	27_	26-	25_
11 -31-	32	33		<u> </u>	
13			34	35_	36

A. Description of original monument and accessories and/or subsequent restoration:

Not set in G.L.O. survey

10-03-86 Ankrom L.C.R.C. 620 Found no evidence of record iron

8-3-76 Kattouah (132) 2-194 See survey for details

Set C.I. by S.P.M. Wit.-South 67.65 E 1/4 Cor, Sec. 24

N67W 47.87 10" Poplar S83E 78.63 14" W. Pine S48E 65.60 6" Wild Cherry

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" x 18" C.I. Excavated and found no further evidence. Found all 1986 witnesses. Measured South 2641.80 and North 2642.14 to Section Corners. Measured 180 degrees 00 minutes angle at corner Found fence at North 1/8 line to be at mid-point. Moved corner to S.P.M. from correct SW Section Corner (Ankrom set SW Corner at wrong falling from Standard Corner). Corner moved 1.16 ft. North.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Set 3/4" x 18" Gas Pipe with Brass cap stamped "Midland Co. Remon. Cor. P.S. 27458" in Monument Box. Accepted as best available evidence of the accepted position of the comer.

Witnesses:

South 68.81', - 1/2' iron at E 1/4 Cor., Sec. 24, T14N, R3W (OBT)

\$83E 78.60', nail & tag, 28" W. Pine (OBT) \$52E 65.86', nail & tag, 8" Wild Cherry (OBT)

N61E 36.76', nail & tag, P.P.

Signed by Surveyor's Michigan License No.

Date 10-31-97

MARK R. ROBISON **PROFESSIONAL** SURVEYOR 44

27458 OFESSION