
LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:						
Midland		Located In			Comer Code #	
(County)						
1. Public Land Survey	20	T T		R_ R		
Property Controlling in Section	S 31	T _	15N	R	1W	1
	S 31	_ T	15N	R_	1W	8
Miscellaneous Property in Section	s	Т		R		
	S	T		R.		
4. Lot No:	Recorded Plat:					
5. Private Claims:						
_						<u> </u>

Register of Deeds Stamp & File Number



requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

I, Craig W. McVean, in a field survey on Oct. 5, 2011 do hereby state that under

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- <u>1</u> **1919** F. J. Gibbs County Survey Record L. 1, p. 400, 401. Set gas pipe for corner.
 - 1977 Record Survey L. 3, p. 432 and field notes -J. A. Schafer - Set 7/8" rod, 2.0' Long
- $\underline{8}$ 1919 F. J. Gibbs County Survey Record L. 1, p. 400 Set gas pipe at average distance on true line.
- 1972 Unrec. Survey D. B. Whittier Job #9933 Set
- 1977 Record Survey L. 2, p. 432 & notes -Jerome A. Schafer -- Fd. 3/4" iron pipe.
- B. Description of comer evidence found and/or method applied in restoring or re-establishing corner:
- 1 W 1/16 comer common to Sections 30 & 31 Found 1 1/2" I.D. x 1.6' long iron pipe in N-S down fence remains. Fence corner E, W & S is 28.5' North. Also found 5/8" rebar per Jerome Schafer with steel sign post as guard is S48°11'E 4.20' of Gibb's pipe and 3.5' E of N-S fence remains. Did not accept Schafer's iron since it is in conflict with Gibbs' historical position and fence occupation. 1 1/2" iron pipe accepted as best available evidence of the position of the corner.
- 8 CW 1/16 corner Section 31 Found 1/2" capped iron #9433 -0.8' below bit surface. Removed 1/2" CIR and found 1 1/4" O.D. iron pipe - 1.6' below Bit. Centerline of E-W Bit. Rd. is 6' S. Accepted 1 1/4" pipe as best available evidence of the position of the corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 1 Drove stamped 2" Aluminum cap on 5/8" x 34" rebar inside found 1 1/4" iron pipe. N64°E 54.66' to set nail & tag in NW side 6" Oak S05°E 31.62' to set nail & tag in E. side 7" Red Maple N88°W 39.53' to set nail & tag in S. side 5" Elm N52°W 21.37' to set nail & tag in NE side 6" Oak S48°11'E 4.20' to fd. 5/8" rebar
- 8 Raised 1 1/2" iron pipe with stamped 2" Aluminum cap on 5/8" x 24" rebar set in concrete flush with asphalt road. S43°E 53.71' to set nail & tag in SW side 18" Ash S70°W 42.60' to set 1/2" x 12" rebar N80°W 185.87' to set nail & tag in N. side P. Pole N28°W 41.20' to chiseled 'X' in SW side 5" steel post North 33.00' to Fd. 3/4" iron pipe with 1/2" CIR alongside.

Surveyor's Michigan License No.:

10/2012 Date:

MICHIGAN CRAIG W. MCVEAN 39bc 39bc 39bc Selow