

APPROVED LAND CORNER  
P.A. 345 OF 1990 LAND CORNER RECORDATION CERTIFICATE  
MIDLAND COUNTY Filing Requirement of Act 74, Mich. P.A. 1970  
Midland County Remonumentation

484

For Corners in

Midland

(County)

Located In:

Corner Code#:

1. Public Land Survey

T. 15N R. 2W

J-1

T. R.

T. R.

2. Public Controlling  
in Section

S.

T.

SURVEY &  
REMONUMENTATION

3. Miscellaneous

S.

T.

R.

FEB 23 2001

Property in Section

S.

T.

R.

4. Lot No.

Recorded Plat

SECTION

5. Private Claims

STATE OF MICHIGAN  
MIDLAND COUNTY  
REMONUMENTATION & FILED

10/6/2000 10:36:48 AM

SCOTT I. HAINES  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Mark R. Robison, in a field survey on July 27, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

Not Set in G.L.O.

No records of re-surveys

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found no evidence of corner. Found J-13 T16N, R2W. Set corner position on standard line between J-13 and I-13, T16N, R2W, and at equal distances from I-1 and K-1 (2650.45 feet both ways) corner falls 3 feet South of North edge of asphalt. There is an 8 foot deep ditch on North side of road. Accepted as best position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" x 18" pipe with brass cap stamped "Midland County Remon Cap marked P.S. #27458" in Mon. Box.

Witnesses:

S68°E, 55.84' - 1/2" Iron on S. Side asphalt

S38°E, 26.10' - 1/2" Iron on S. Side asphalt

S45°W, 24.38' - 1/2" Iron on S. Side asphalt

East, 34.19' - J-13, T16N, R2W



Signed by

*Mark R. Robison*

Date

9-15-2000

Surveyor's Michigan License No. 27458

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975  
REVISED JAN., 1983