

APPROVED LAND CORNER

P.A. 345 OF 1990  
MIDLAND COUNTY

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Midland County Remonumentation

485

For Corners in

Midland

(County)

Located In:

Corner Code#:

1. Public Land Survey

T. 15N R. 2W

K-1

T. R.

T. R.

2. Public Controlling  
in Section

S. T.

T. R.

3. Miscellaneous

S. T.

T. R.

Property in Section

S. T.

T. R.

4. Lot No.

Recorded Plat

5. Private Claims

SECTION

STATE OF MICHIGAN  
MIDLAND COUNTY  
REMONUMENTATION & FILED

10/6/2000 10:36:48 AM

SCOTT I. HAINES  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Mark R. Robison, in a field survey on July 14, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

1832, Wright

78.50 Int. N. Bdy. 0.50 West of Post

B. Ash 16" S77°E, 18 LINKS

Elm 10" S40°W, 47 LINKS

1984, Gilbert (132) 3-616

Same as (132) 3-435

Undated, Circa 1900, Gibbs, CSR

Drove gas pipe 50 West of

corners to 35 & 36 Warren

Meas. 40.24 East

Meas. 38.56 South

1986, Lapham, LCRC #618

Fd C.I.

East, 33.05 P.K. Nail

S70°E, 76.7 P.P.

N45°E, 92.55 P.P.

1982 Gilbert, (132) 3-435

1/2" Rod

M65°E, 92.58 P.P.

S68°E, 76.81 P.P.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 1/2" x 18" C.I. and all 1982 and 1986 witnesses. Excavated to original ground and found no other evidence. Corner falls 10 feet West of C.L. T-Road South. There is a 10 feet deep drain on West side of road South. Measured East 2653.85 to L-1 and West 2650.41 to J-1. Meas. East 33.06 to K-13 T16N, R2W. Accepted as best available evidence of the perpetuation of the original corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" x 18" pipe w/brass cap stamped with "Midland County Remon P.S. #27458" in Mon. Box

Witnesses:

N25°W, 25.88' - Top C.L. 48" CMP

N65°E, 92.44' - N & T in P.P. (OBT)

S65°E, 76.66' - N & T in P.P. (OBT)

East, 33.06' - K-13, T16N, R2W, (OBT)

Corner falls on line between J-13 and K-13 T16N, R2W

Signed by

*Mark R. Robison*

Date

9-15-2000

Surveyor's Michigan License No. 27458

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975  
REVISED JAN., 1983

