

**REMON. COR. F-9, LARKIN TWP.
LAND CORNER RECORDATION CERTIFICATE**
Filing Requirement of Act 74, Mich. P.A. 1970

516

For corners in
Midland
(County)

Located in: Corner Code #

1. Public Land Survey

T 15N R 2E F-9

2. Property Controlling
in Section

T R
T R SURVEY &
T R REMONUMENTATION

3. Miscellaneous
Property in Sec.

S T R
S T R FEB 28 2001
S T R
S T R

4. Lot No. Recorded Plat

5. Private Claims

SECTION

STATE OF MICHIGAN
MIDLAND COUNTY
REMONUMENTATION & FILED

12/28/2000 8:44:27 AM

SCOTT I. HAINES
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, RODNEY CLAYPOOL, in a field survey on May 25, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F-9 1/4 Corner common to Sections 21 and 28

Survey by Glo, 1830's.
Survey by M. Hunter, 1952, 1959, 3/4" pipe
Survey by J. Schafer, 1978, 1983, L-3, P-441, found 3/4" pipe
Survey by D. Ledy, 1991, found 1/2" rod and cap
Survey by J. Jones, 1991, 1993, found iron and cap
LCRC by J. Schafer, 1978, found 3/4" pipe in monument box
LCRC by J. Erickson, 1982, found 5/8" pipe in monument box
LCRC by P. Lapham, 1983, found monument box
LCRC by D. Ledy, 1991, set 1/2" rod and cap per recorded survey L3, P441, 442

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-9 1/4 Corner common to Sections 21 and 28

Found 1/2" rod and cap at position per surveys by M. Hunter, J. Schafer, D. Ledy, J. Jones and LCRC's by J. Schafer, J. Erickson, F Lapham and D. Ledy.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-9 1/4 Corner common to Sections 21 and 28

Replaced rod with 5/8" rod and brass cap stamped Midland Co. Remon Cor PS 29241 in monument box and is accepted as the best available evidence of the position of the accepted corner.

N 10 Deg E, 36.23, pk nail in power pole
N 15 Deg W, 39.53, nail and plastic disc in 40" Willow
S 10 Deg W, 48.90, nail and disc in power pole
S 60 Deg W, 86.43, nail and plastic disc in 6" Pine
E-9 to F-9, 2646.14M, F-9 to G-9, 2636.94M

Signed by Rodney D. Claypool
Surveyor's Michigan License No. 29241

Date 12-22-00
Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1971
Revised Jan., 1983

APPROVED LAND CORNER
P.A. 345 OF 1990
MIDLAND COUNTY

12/22/00

