

**REMON. COR. H-9, LARKIN TWP.  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970**

**517**

For corners in  
Midland

(County)

Located in: Corner Code #

1. Public Land Survey

T 15N R 2E H-9

T     R    

T     R    

T     R    

2. Property Controlling  
in Section

S     T     R     **SURVEY &**

S     T     R     **REMONUMENTATION**

3. Miscellaneous  
Property in Sec.

S     T     R     **FEB 23 2001**

S     T     R    

4. Lot No.           , Recorded Plat            **SECTION**

5. Private Claims           

I, **RODNEY CLAYPOOL**, in a field survey on May 25, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H-9 ¼ Corner common to Sections 22 and 27

Survey by Glo, 1830's, set post  
Survey by M. Hunter, 1958, 1960, 1966, found  
Survey by D. Whittier, 1955, 1967, 1968, found - set concrete monument  
Survey by Hunter-Whittier, 1974, 1975, found concrete monument  
Survey by M. MacDonald, 1984, found ½" iron  
Survey by J. Jones, 1994, found  
LCRC by J. Schafer, 1974, found concrete monument  
Kurtz Subdivision, L-F, P-42, 1967

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-9 ¼ Corner common to Sections 22 and 27

Found monument in monument box per surveys by M. Hunter, D. Whittier, Hunter-Whittier, M. MacDonald, J. Jones and LCRC by J. Schafer, and fits Kurtz Subdivision.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-9 ¼ Corner common to Sections 22 and 27

Set 5/8" rod and brass cap stamped Midland Co. Remon Cor PS 29241 on monument and is accepted as the best available evidence of the position of the accepted corner.

S 5 Deg W, 31.20, nail and plastic disc in power pole  
S 20 Deg W, 32.16, centerline top fire hydrant  
N 10 Deg W, 45.60, nail and disc in power pole, Rec. 45.60  
S 60 Deg E, 92.02, nail (new) in 24" Maple clump, Rec. 93.19  
S 55 Deg E, 63.62, face of 15" Spruce, Rec. 64.4 face 4" Spruce

Signed by Rodney D. Claypool  
Surveyor's Michigan License No. 29241

Date 12-12-00

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971  
Revised May 14, 1971  
Revised Jan., 1983


STATE OF MICHIGAN  
MIDLAND COUNTY  
REMONUMENTATION & FILED

12/28/2000 8:44:27 AM

SCOTT I. HAINES  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													



IMPROVED LAND CORNER  
P.A. 345 OF 1990  
MIDLAND COUNTY

12/27/00 JHJ