

APPROVED LAND CORNER  
P.A. 345 OF 1990  
MIDLAND COUNTY  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970  
Midland County Remonumentation

503

8/134/00019  
For Corners in  
Midland

(County)

Located In:

Corner Code#:

1. Public Land Survey

T. 16N R. 1E G-2

T.      R.      SURVEY &  
T.      R.      REMONUMENTATION

2. Public Controlling  
in Section

S.      T.      R.     

3. Miscellaneous

S.      T.      R.      FEB 23 2001

Property in Section

S.      T.      R.     

4. Lot No.     

Recorded Plat      SECTION     

5. Private Claims     

STATE OF MICHIGAN  
MIDLAND COUNTY  
REMONUMENTATION & FILED

10/6/2000 10:36:48 AM

SCOTT I. HAINES  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Mark R. Robison, in a field survey on July 5, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

1832, Parke  
40.00 Set 1/4 Sec. Post  
Aspen 9" N50°W 21 LINKS  
Aspen 6" S32°E, 9 LINKS

1956, Courtright, L.-D, Pg. 10  
Thomas Shores Subdivision No. 2

8-11-1953, Hunter, Field notes, Unrecorded  
"Found 6" round spot in white sand. Followed  
down about 6". No question about it being a  
post." Set 3/4" pipe. In line with fence E-W.  
S88W, 40.48 Tag in P.P.  
S45E, 40.20 Tag in 14" Pine

1986, Jones (132) 3-923  
Used Corner in survey to North  
No Witnesses. Meas. North 1321.19  
to 1/8 corner

1994, Jones (132) 5-199  
Fd 3/4" pipe  
West, 40.46' N & D in P.P.  
N55°W, 52.80' P.K. in end F.P.  
N35°E, 62.35' Nail in 15" Pipe  
S45°E, 36.88' Nail in 8" Apple

1954, Hunter, L.-C, Pg. 16  
Thomas Shores Subdivision

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 3/4" x 18" pipe in asphalt pvm't. Found three 1994 witnesses and one 1953 witness and measured North 1321.20 to 1/8 corner pipe 1986 survey and Plats of Thomas Shores & Thomas Shores Subdivision No. 2 (1/8 corner checked as P.O.B. of Plats). Measured 180° 00', 2641.29 feet South to G-3. Accepted 3/4" pipe as best available evidence of the perpetuation of the original position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Ser 3/4" x 18" pipe with brass cap stamped "Midland County Remon Corner, P.S. #27458. in Mon. Box.

Witnesses:

S42°W, 48.62' - N & T in 16" Pine  
West, 40.40' - N & T in P.P. (OBT)  
N40°E, 48.80' - N & T in 20" Pine  
S46°E, 36.87' - N & T in 4" x 5" Tw. Apple (OBT)  
N34°E, 62.31' - Nail in 16" Pine (OBT)

Signed by

*Mark R. Robison*

Surveyor's Michigan License No. 27458



9-15-2000

APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28,

REVISED MAY 14,  
REVISED JAN.