

Land Corner Recordation Certificate
Attachment B to 2016 Annual Grant Agreement
Authority: MCL 54.205 and R54.202

This form is **ONLY** for corners filed under the 2016 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 – 54.210d and 2016 State Survey and Remonumentation Grant Agreement

Notes:

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Midland County

Edenville and Jerome Twp's.

Corner Type	Survey Township				Corner Code
Original Public Land Survey Corner	T	16N	R	1W	F13
• MCL 54.202(g)	T	15N	R	1W	F1
• MCL 54.262(g)	T		R		
	T		R		
Property Controlling Corner	S		T	R	
• MCL 54.202(i)	S		T	R	
• MCL 54.262(h)	S		T	R	
	S		T	R	
Protracted Public Land Survey Corner	T		R		
• MCL 54.202(k)	T		R		
• MCL 54.262(i)	T		R		
	T		R		

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2	6			5		4		3		2		1		2
3														3
4	7			8		9		10		11		12		4
5														5
6	18			17		16		15		14		13		6
7														7
8	19			20		21		22		23		24		8
9														9
10	30			29		28		27		26		25		10
11														11
12	31			32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A: Corner(s) History

F13 & F1 – 1830 – GLO – R. Clark, Jr.- ¼ Sec. Corner a Hemlock 10" dia.

Part B: Surveyor’s Report on Perpetuation or Monumentation of Corner(s)

F13 & F1 – Standard ¼ Corner common to Section 33, T16N, R1W and Sec. 4, T15N, R1W – No evidence of GLO corner tree was found. Searched for line tree evidence east & west but nothing conclusive was found. Set 4” DNR Aluminum cap on 1” x 36” long galvanized iron pipe by single proportion along parallel between “C1-C13” and “I1-I13”. Centerline of east-west gravel road is 49’ ± south. DNR monument is accepted as a careful and faithful re-establishment of the position of the original corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner(s)

F13 & F1 – Stamped 4” DNR Aluminum cap on 1” x 36” galvanized iron pipe. Set Blue Composite post 1’ South
N07°W 26.33’ to set nail & tag in east side 25” White Oak
S65°E 3.49’ to set nail & tag in northeast side 9” Oak scribed ‘XBT’
S40°W 27.40’ to set nail & tag in southeast side 13” Oak scribed “XBT”
N85°W 13.74’ to set nail & tag in south side 6” Red Maple

Date of Observation	Latitude	Longitude	Datum and Adjustment Year	Epoch Date
August 23, 2016	N43°43’36.9862”	W84°26’16.3467”	NAD83(2011)	2010.00

Position set by double side shot from 3 GNSS control points.
Points determined from two base lines to each point from 2 local OPUS base stations.

I, Craig W. McVean, in a field survey on August 23, 2016, certify under the requirements of the State Survey and Remonumentation Act, 1990 PA 345, MCL 54.261 to 54.279, and the Corner Recordation Act, 1970 PA 74, MCL 54.201 to 54.210d, that the corner(s) identified and described hereon has been perpetuated or monumented as described in Parts A, B, and C above, pursuant to the laws and rules of the State of Michigan.

Craig W. McVean

Craig W. McVean

12/7/2016

Date

Professional Surveyor’s License No.: 39088

Department of Natural Resources, 8015 Mackinaw Trail, Cadillac, MI 49601



I, Brian D. Ferguson, state that the corner(s) identified and described hereon and perpetuated or monumented as described in Parts A, B, and C above was presented to and reviewed by the Peer Review Group on August 3, 2016 and is accepted for filing in the Midland County Remonumentation Program.

Brian D. Ferguson

Brian D. Ferguson

Date

Professional Surveyor’s License No.: 26454