# Land Corner Recordation Certificate Attachment B to 2016 Annual Grant Agreement

Authority: MCL 54.205 and R54.202

This form is ONLY for corners filed under the 2016 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 - 54.210d and 2016 State Survey and Remonumentation Grant Agreement

#### Notes:

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Midland County Edenville & Jerome Twps. Corner **Corner Type Survey Township** Code Original Public Land E13 Survey Corner 16N R **1W**  MCL 54.202(g) MCL 54.262(g) 3 4 5 5 **Property Controlling** Corner R 6 18 -17-<del>16</del> -15 13 6 14 MCL 54.202(i) R 7 MCL 54.262(h) S R 20 22 23 24 8 S 9 30 28 27 26 25 10 Protracted Public Land Survey Corner 11 MCL 54.202(k) R 12 35 36 12 MCL 54.262(i) R

#### Part A: Corner(s) History

E13 & E1 - 1830 - GLO - R. Clark, Jr. - Set Post

- 1) Pine 36" N43°E 70 L.
- 2) Aspen 5" N78°W 47 L
- 1852 GLO Subdivision T15N, R1W A. Burt S0°39'W Correcting between Sec. 4 & 5
  - 3) Aspen 5" S61°E 26 L.
  - 4) Aspen 10" S65°W 61 L.

Land Corner Recordation Certificate
Attachment B to 2016 Annual Grant Agreement
T16-15N R1W Code <u>E13 & E1</u>
Page 2 of 2

### Part B: Surveyor's Report on Perpetuation or Monumentation of Corner(s)

E13 & E1 – Standard corner common to Section 32 & 33, T16N, R1W and Sec. 4 & 5, T15N, R1W – No GLO evidence found. Could not find any remains of large pine stump. Set stamped 4" DNR Aluminum cap on 1" x 36" galvanized iron pipe by single proportion on the line of parallel between 'C1 – C13' and 'I1 – I13'. Measured east 330' ± to east edge of old channel of Mud Creek (5 chains stream 19 SE – GLO). DNR monument accepted as a careful and faithful re-establishment of the position of the original corner.

## Part C: Field Evidence of Perpetuation or Monumentation of Corner(s)

E13 & E1 – Stamped 4" DNR aluminum cap on 1" x 36" long galvanized iron pipe. Set blue composite post 1' South N19°E 55.62' to set nail & tag in east side 26" Oak S43°E 36.76' to set nail & tag in northeast side 26" Oak S01°E 58.56' to set nail & tag in west side 8" Oak scribed 'XBT' N80°W 12.95' to centerline of 1" Oak at blaze

Date of Observation	Latitude	Longitude	Datum and Adjustment Year	Epoch Date
8/23/2016	N43°43'37.1938"	W84°26'52.2494"	NAD83(2011)	2010.00

Position set by RTK from Coleman CORS station and checked by two static GNSS baselines from 2 Local OPUS Base stations

I, Craig W. McVean, in a field survey on 08/23/2016, certify under the requirements of the State Survey and Remonumentation Act, 1990 PA 345, MCL 54.261 to 54.279, and the Corner Recordation Act, 1970 PA 74, MCL 54.201 to 54.210d, that the corner(s) identified and described hereon has been perpetuated or monumented as described in Parts A, B, and C above, pursuant to the laws and rules of the State of Michigan.

54.201 to 54.210d, that the corner(s) identified and described hereon has been perpendescribed in Parts A, B, and C above, pursuant to the laws and rules of the State of Michigan	
Cring W. Millen 12/7/2016	ATE OF MICHIG
Craig W. McVean Date	CRAIG W.
Professional Surveyor's License No.: 39088	PROFESSIONAL SURVEYOR O
Department of Natural Resources, 8015 Mackinaw Trail, Cadillac, MI 49601	OFESSIONAL SE

I, Brian D. Ferguson, state that the corner(s) identified and described hereon and perpetuated or monumented as described in Parts A, B, and C above was presented to and reviewed by the Peer Review Group on 08/03/2016 and is accepted for filing in the Midland County Remonumentation Program.

Brian D. Ferguson		Date
Professional Surveyor's License No.:	26454	