## **Land Corner Recordation Certificate**

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Craig W. McVean				Field Survey Date: June 26, 2017					
For corner(s) in: Midland  Original Public Land Survey Corner			County						
			Corner Code						
S 32 & 33	T 16	N R 01W	E12						
S	т	R		ABO	C D I	E F (	з н	IJ	K L M
S	Т	R		1			1		
s	т —	R		2 6	5	4	3	2	1-1-2
				3		i	i i	-	
Property Controlling Corner			Corner Code	4 7	8	ģ	- 10 -	- 11	12 4
S	T_	R		5					
S	т	R			4.7				
S	т —	R		6 18	- 17	16	- 15 -	- 14	13 6
S	т	R		7		1	1		17
	- 100 miles			8 19	20	21	22	23	24 8
Property Corner			Corner Code	9 +		1	-		
\$	T_T	R		10 30	29	28	27	26	25
s		R			2.5	20	21	20	1 6 1
S	т —		-	11					
S	_ <sub>T</sub> _	R		12 - 31 -	- 32	- 33 -	- 34	- 35	36
			: <del>\</del>	13 A B (	D I	E F (	G H		C L M
Protracted Public Land Survey Corner			Corner Code	"A B (	י ט כ	E F (	<i>э</i> П	IJŀ	K L M
S	Т	R							
s	$ _{T}-$	R							
s	т т	R		•					
s	— <u>;</u> —	'`		•					

## Part A: Corner History

E12 -1/4 corner common to section 32 & 33, T16N, R1W-1832 -GLO- H. Parke, A Pine 18" a qr. sec. corner

- -1852 A. Burt GLO Dependent Resurvey Set Post in stump of old corner 1) W. Birch 6" S59"W 18 L. 2) W. Pine 18" N32"E 53 L.

## Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

E12 - 1/4 corner common to section 32 & 33, T16N, R1W-

Searched for evidence of two pines stumps that would conform to the GLO record but could only find one in the search area. Also searched for line tree evidence to the south and found several pine stumps that could have been line trees but nothing that would conclusively fit a position for the ¼ corner in regard to the pine stump found in the search area. Thus set a stamped 4" DNR aluminum cap on a 1" x 36" long galvanized iron pipe by single proportion and holding the record 1852 GLO angle at 'E12' between reestablished positions at 'E13' and 'E11'. Measured grid bearing and distance of S00°08'11"W 2621.25' [South 39.90 (2633.4') –GLO] to 'E13' and N00°31'12"E 2640.29' [N0°23'E 40.19 (2652.54')-GLO] to 'E11'. Measured north 146'+/- 5' to enter marsh vs. GLO calls for leave thicket North 2.1 CH C. SE & NW. Measured south 1702' to bottom of bank of bottomlands and now also being the edge of stream vs. 1709'-GLO. DNR monument is 5'+/- north of low area. DNR monument accepted as a careful and faithful reestablishment of the position of the original corner.

5/2017

## Part C: Field Evidence of Perpetuation or Monumentation of Corner

E12 -1/4 corner common to section 32 & 33, T16N, R1W-

Stamped 4" DNR Aluminum Cap on 1" x 36" long galvanized iron pipe. Set Blue Composite Post 1' South S85°W 5.80' to set Nail & Tag (N & T) in N side 4" R. Maple N17°W 4.20' to set N & T in W side 9" Oak scribed 'XBT' N52°E 10.18' to set N & T in side of 7" Oak S55°E 10.08' to set N & T in NE side 4" R. Maple side scribed 'XBT'

CRAIG W.
MCVEAN
PROPESSIONAL
SURVEYOR
NO.
39088

Craig W. McVean

Professional Surveyor's License No.: 39088

Prepared By: Craig W. McVean Michigan Dept. of Natural Resources 8015 Mackinaw Trail Cadillac, Michigan 49601