

REMON CORNER A-5, EDENVILLE TWP.
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

533

For corners in
Midland

(County)

Located in: Corner Code #

1. Public Land Survey T 16N R 1W A-5
T R
T R
T R SURVEY &
2. Property Controlling S T REMONIMENTATION
in Section S T R
3. Miscellaneous S T R FEB 23 2001
Property in Sec. S T R
4. Lot No. _____ Recorded Plat _____ SECTION _____
5. Private Claims _____

STATE OF MICHIGAN
MIDLAND COUNTY
REMONIMENTATION & FILED

12/28/2000 8:44:27 AM

SCOTT I. HAINES
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, RODNEY CLAYPOOL, in a field survey on June 11, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- A-5 Corner common to Sections 7 and 18 on West townline
Survey by Glo, 1831, set post at 34 links South of M-5

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- A-5 Corner common to Sections 7 and 18 on West townline
Set 5/8" rod and cap on controlling Township line at Glo offset distances from M-5. (Between M-5 and M-6)


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- A-5 Corner common to Sections 7 and 18 on West townline

Corner is a 5/8" rod and brass cap stamped Midland Co. Remon Cor. PS 29241 and is accepted as the best available evidence of the position of the accepted corner.

N 35 Deg W, 64.78', chiseled "+" in North end concrete pipe
West 38.09', chiseled "+" in South end concrete pipe
S 70 Deg W, 50.22', nail in South side telephone pole
S 70 Deg E, 65.08', MDOT nail and disk in power pole
North 22.44', Warren Twp. corner M-5
North 30', centerline road to East
East 4.5', centerline M-18

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													



Signed by Rodney D. Claypool
Surveyor's Michigan License No. 29241

Date 12-26-00

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1971
Revised Jan., 1983

