

REMON CORNER A-9, EDENVILLE TWP.
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

537

For corners in
Midland

(County)

Located in: Corner Code #

1. Public Land Survey

T 16N R 1W A-9

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. _____ Recorded Plat _____

5. Private Claims _____

SECTION

STATE OF MICHIGAN
MIDLAND COUNTY
REMONUMENTATION & FILED

12/28/2000 8:44:27 AM

SCOTT I. HAINES
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, **RODNEY CLAYPOOL**, in a field survey on **June 23, 1999**, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-9 Corner common to Sections 19 and 30

Survey by Glo, 1830, set post 40 links South
Survey by F. Gibbs, 1901, set post
Survey by MDOT, 1937, used corner
Survey by D. Whittier, 1969, found monument box
Survey by J. Jones, 1994, set pk from old witnesses
LCRC by P. Lapham, 1979, monument box

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-9 Corner common to Sections 19 and 30

Found pk nail at position per surveys by MDOT, D. Whittier, J. Jones and LCRC by P. Lapham.


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-9 Corner common to Sections 19 and 30

Replaced pk nail with $\frac{3}{4}$ " pipe and brass cap stamped Midland Co. Remon Cor. PS 29241 in monument box and is accepted as the best available evidence of the position of the original corner.

S 63 Deg E, 41.11', nail and MDOT disk in power pole
N 82 Deg W, 63.39', South corner project marker (Rec.)
S 55 Deg W, 147.74', NE corner store (New)
N 40 Deg E, 88.70', SW corner block building (old school) (Rec.)
South 18.57', Warren Township corner M-9 (Rec.) (GLO jog calls for 40 links, 26.45 ft.)

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													



Signed by Rodney D. Claypool
Surveyor's Michigan License No. 29241

Date 12-26-00

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1971
Revised Jan., 1983

