REMON CORNER A-11, EDENVILLE TWP. LAND CORNER RECORDATION CERTIFICATE

539

	Filing Requirement of Act 74, Mich. P.	
For corners in Midland (County)	Located in:	Corner Code #
1. Public Land Survey	T 16N R 1W T R T R	A-11
Property Controlling in Section Miscellaneous	T _ R _ R _ R _ R _ R _ R _ R _ R _ R _	SURVEY & MONUMENTATION FEB 2.3 2001

STATE OF MICHIGAN KIDLAND COUNTY REMONUMENTATION & FILED

12/28/2000 8:44:27 AM

SCOTT I. HAINES REGISTER OF DEEDS

и

K L

Register of Deeds Stamp & File Number

R c n Ε

Δ

Property in Sec. _, Recorded Plat _ SECTION 4. Lot No. 5. Private Claims

I. RODNEY CLAYPOOL, in a field survey on June 23. 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the interior, Bureau of Land Management or by a decree of a Court of Law; re-established, of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below: with the mininger board of parts of veryons of by a people's a source monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- 3 À 5 6 2 12 10 9 8 5 13 15 14 17 16 18 6 7 24 23 21 22 19 20 8 25 26 28 27 29 30 10 36 35 34 33 32 31 12
- A. Description of original monument and accessories and/or subsequent restoration:
- Corner common to Sections 30 and 31 on West townline

Survey by Gio, 1830's, set post Survey by Gio, 1830's, set post Survey by F. Gibbs, 1908, set gas pipe Survey by MDOT, 1941, used corner Survey by D. Whittier, 1970, monument box Survey by J. Jones, 1993, found 1" iron in monument box LCRC by P. Lapham, 1979, monument box



- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Corner common to Sections 30 and 31 on West townline A-11

Found 5/8" rod in monument box at position per surveys by F. Gibbs, MDOT, D. Whittier, J. Jones and LCRC by P. Lapham.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- Corner common to Sections 30 and 31 on West townline

Replaced rod with 5/8° rod and brass cap stamped Midland Co. Remon Cor. PS 29241 and is accepted as the best available evidence of the position of the original corner.

S 35 Deg E, 71.18', nail and MDOT disk in 15" Pine (Rec.)
N 85 Deg E, 21.14', pk nail in top guardrail post
N 25 Deg E, 72.45', chiseled "+" in East end of Southeast wingwall
N 20 Deg W, 69.00', chiseled "+" in West end of Southwest wingwall
N 50 Deg W, 62.90', nail in post (Rec.)
S 55 Deg W, 108.48', pail and MDOT disk in 18" Cottonwood S 55 Deg W, 108.48', nail and MDOT disk in 18" Cottonwood South 2.11', Warren Twp. corner M-11 (GLO calls for 3 links jog 1.98 ft)

12-26-00 Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971 Mayor Signed by Address No. 29241 Revised Jan., 1983

